



## CSA Aircraft Maintenance

Ogden, UT 84405 USA

Phone [REDACTED]

Email: [REDACTED]

Date: 12/10/2020, 9:22 AM

## CUSTOMER INFORMATION

Netgenesis Inc

Reg. No: 577CP

2008 Cirrus Design Corp Sr22

Current A/C TT: 722.7, Tach: 722.7

A/C Serial: 3345

Customer Invoice  
**Work Order: 9100-12-2020**

**Total Balance Due [REDACTED] (See Below For Cost Detail)**

**Item: 1 - Airworthy / Airframe****Discrepancy**

AIRFRAME ANNUAL/100 INSPECTION

**Hours****Subtotal****Corrective Action**

AIRCRAFT HAS BEEN INSPECTED FOR AN ANNUAL INSPECTION PER FAR 43 APPENDIX D USING THE CIRRUS DESIGN SR22 INSPECTION CHECKLIST 05-20 AS A REFERENCE AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED AT THIS DATE AND TIME.

**Inspection Information:**

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

| Qty | Unit | Part Number  | Description                | Serial Number | Unit Price | Subtotal |
|-----|------|--------------|----------------------------|---------------|------------|----------|
| 1   | EA   | LOG AIRFRAME | LOG BOOK- AIRFRAME (Taxed) |               |            |          |

**Item: 2 - Airworthy / Airframe****Discrepancy**

ELT OPERATIONAL CHECK PER FAR 91.207 (d)

**Hours****Subtotal**

0.50

**Corrective Action**

ELT OPERATIONAL CHECKED SATISFACTORY PER FAR 91.207d. BATTERY EXPIRATION DATE MAR/2021

**Inspection Information:**

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

**Item: 3 - Airworthy / Airframe****Discrepancy**

AD RESEARCH

**Hours****Subtotal****Corrective Action**

AD SEARCH C/W USING ATP REVISION 12/08/2020

**Inspection Information:**

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

---

**Item: 4 - Airworthy / Airframe**

**Discrepancy**

AIRCRAFT LUBRICATED PER SR22 AMM CHAPTER 12-20

Hours

Subtotal

**Corrective Action**

AIRCRAFT LUBRICATED PER SR22 AMM CHAPTER 12-20 C/W

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

[REDACTED]

---

**Item: 5 - Airworthy / Airframe**

**Discrepancy**

TORNADO ALLEY TURBOCHARGER SYSTEM INSPECTION FOR CONTINUED AIRWORTHINESS PER DOC# 22-6460004 REV A DATED 04/10/09.

Hours

Subtotal

**Corrective Action**

TORNADO ALLEY TURBOCHARGER SYSTEM INSPECTION FOR CONTINUED AIRWORTHINESS C/W PER DOC# 22-6460004 REV A DATED 04/10/09.

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

[REDACTED]

---

**Item: 6 - Airworthy / Airframe**

**Discrepancy**

PRECISE FLIGHT BUILT IN-OXYGEN SYSTEM INSPECTION FOR CONTINUED AIRWORTHINESS PER DOCUMENT #102NMAN003. NO DEFECTS NOTED THIS DATE

Hours

Subtotal

**Corrective Action**

PRECISE FLIGHT BUILT IN-OXYGEN SYSTEM INSPECTION FOR CONTINUED AIRWORTHINESS C/W PER DOCUMENT #102NMAN003. NO DEFECTS NOTED THIS DATE

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

[REDACTED]

---

**Item: 7 - Airworthy / Airframe**

**Discrepancy**

TAT SB09-01 INSPECTION OF EXHAUST MANIFOLDS

Hours

Subtotal

**Corrective Action**

TAT SB09-01 INSPECTION OF EXHAUST MANIFOLDS C/W

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

[REDACTED]

---

**Item: 8 - Airworthy / Airframe**

**Discrepancy**

TAT SI08-01 REV. A INSPECT FOR THE POSSIBILITY OF A RESTRICTION IN THE CRANKCASE BREATHER. C/W

Hours

Subtotal

**Corrective Action**

TAT SI08-01 REV. A INSPECT FOR THE POSSIBILITY OF A RESTRICTION IN THE CRANKCASE BREATHER.

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

[REDACTED]

**Item: 9 - Airworthy / Airframe**

**Discrepancy**

TAT SB10-02 INSPECTION SUPPLEMENTAL TAIL PIPE HANGERS.

Hours

Subtotal

**Corrective Action**

TAT SB10-02 INSPECTION SUPPLEMENTAL TAIL PIPE HANGERS. C/W

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

**Item: 10 - Airworthy / Airframe**

**Discrepancy**

GARMIN GTX 335R ICA

Hours

Subtotal

**Corrective Action**

GARMIN GTX335 ICA C/W PER GARMIN MANUAL #190-00734-11 REV. 7

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

**Item: 11 - Airworthy / Airframe**

**Discrepancy**

INDUCTION AIR FILTER CLEAN AND LUBE

Hours

Subtotal

**Corrective Action**

INDUCTION AIR FILTER CLEANED AND LUBED

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

**Item: 12 - Airworthy / Engine**

**Discrepancy**

ENGINE 100 HOUR INSPECTION

Hours

Subtotal

**Corrective Action**

ENGINE HAS BEEN INSPECTED FOR A 100 HOUR INSPECTION PER CIRRUS DESIGN SR22 INSPECTION CHECKLIST 05-20 AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED AT THIS DATE AND TIME.

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

| Qty | Unit | Part Number       | Description                                                   | Serial Number | Unit Price | Subtotal |
|-----|------|-------------------|---------------------------------------------------------------|---------------|------------|----------|
| 1   | EA   | CH48108-1         | OIL FILTER, Champion (Taxed)                                  |               |            |          |
| 8   | EA   | Phillips XC 20W50 | OIL-Phillips, X/C 20W50, Aviation, Multiviscosity Oil (Taxed) |               |            |          |

**Item: 13 - Airworthy / Engine**

**Discrepancy**

ENGINE OIL CHANGE

Hours

Subtotal

[REDACTED]

[REDACTED]

**Corrective Action**

ENGINE OIL DRAINED HOT. OIL FILTER REMOVED AND INSPECTED FOR CONTAMINANTS. NONE FOUND. NEW OIL FILTER P/N CH48108-1 INSTALLED AND SAFETIED. ENGINE SERVICED WITH 8 QTS OF XC 20-50W OIL. RAN AIRCRAFT. LEAK CHECK SATISFACTORY

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

[REDACTED]

**Item: 14 - Airworthy / Engine**

**Discrepancy**

ENGINE COMPRESSION CHECK

Hours

Subtotal

[REDACTED]

**Corrective Action**

ENGINE COMPRESSIONS CHECKED AS FOLLOWS, CYL # 1 65/80. # 2 63/80. # 3 65/80. # 4 67/80. # 5 63/80. # 6 62/80. OPERATIONAL CHECKED SATISFACTORY

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

[REDACTED]

**Item: 15 - Airworthy / Prop**

**Discrepancy**

PROPELLER 100 HOUR INSPECTION

Hours

Subtotal

[REDACTED]

**Corrective Action**

PROPELLER HAS BEEN INSPECTED FOR A 100 HOUR INSPECTION IN ACCORDANCE WITH THE SCOPE AND DETAIL OF APPENDIX D PART 43 AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED AT THIS DATE AND TIME.

Inspection Information:

[REDACTED]

**Item: 16 - Airworhty / Airframe**

**Discrepancy**

LINE CUTTERS DATE MFG 06/19

Hours

Subtotal

[REDACTED]

**Corrective Action**

LINE CUTTERS DATE MFG 06/19

Inspection Information:

·Final Inspection: SCOTT GOODFELLOW on 12/08/20

[REDACTED]

**Additional Charges**

**Labor Summary**

Taxed Items:  
Shop Labor, OSR Labor, Misc. Charges, Shop Parts, OSR Parts, , Shop Supplies, Tire Disposal

**Total Labor:**

**Total Parts:**

**Total Shipping:**

**Total Outside Repair:**

**Additional Charges:**

**Tax (7.25 %):**

**Amount Due:**

**Deposits & Credits:**

**Balance Due:**

**Important Information**

AGREEMENT: Customer authorizes: (1) repair and material replacement as indicated herein; (2) operation of aircraft as needed for inspection and testing; (3) a possessory mechanic's lien upon the aircraft and log books securing payment; and, to have and record with the FAA a lien against the aircraft to secure payment. Estimates do not include hidden damage. CSA Aircraft Maintenance will apprise customer of any necessary increases in scope of work, if any, prior to completing such work. Parts Disclaimer: Not all parts installed on your aircraft may have been supplied by Cessna. Parts not supplied by Cessna are not genuine Cessna Product and are not covered by any Cessna warranty or Aftermarket Program, in whole or in part. For details, please see the Service or Parts Manager. The final payment is due upon completion of the work. An interest charge of one and one-half percent (1.5%) per month accrues on past due balances. In the event any balance is not paid as agreed, Customer agrees to pay collection fees, as well as any court costs and reasonable attorney's fees associated with collection hereunder. On credit card payments over \$500.00, please include a 2.75% service cost.

Netgenesis Inc or Authorized Representative

Date