



Memorandum for Record

Fabian Salazar
Air Safety Investigator
National Transportation Safety Board
Investigator in Charge

NTSB Accident Number: WPR21LA070
Aircraft Registration & Make/Model: N261MD / SilverLight Aviation, AR-1
Accident Location: Heber, Utah
Accident Date: December 16, 2020

An autopsy was performed on the pilot by the Utah Department of Health, Office of the Medical Examiner, Taylorsville, Utah. The cause of death was listed as blunt force trauma.