

NATIONAL TRANSPORTATION SAFETY BOARD

ACCIDENT NUMBER:

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ► WPR21LA140

For Use In All Modal Investigations

REGISTERED OWNER (name and address) Boeing Employees Flying Association Inc		IDENTIFICATION NUMBER N2164Z	
		MAKE CESSNA	
LOCATION EVERETT, WA	DATE OF ACCIDENT 03/23/2021	MODEL 172S	
RETAINED BY NTSB REPRESENTATIVE Maja Smith		TITLE Aviation Accident Investigator	DATE 03/23/21
The National Transportation Safety Board has ☒ has not ☐ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released. ☐ NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE Maja Smith		TITLE Aviation Accident Investigator	DATE 12/13/2021
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.) I HEREBY ACKNOWLEDGE: ☒ Receipt of the above described wreckage. ☒ Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNOWLEDGEMENT Wes McKechnie		TITLE Operations Manager	DATE 3/2/2022
ADDRESS [REDACTED] Renton, WA, 98057		PHONE NUMBER & EMAIL [REDACTED]	
REMARKS: NTSB RETAINS ENGINE DRIVEN FUEL PUMP, SERVO AND FUEL MANIFOLD			