



RECORD OF E-MAIL CORRESPONDENCE

**Eric M. Gutierrez
Air Safety Investigator
Western Pacific Region**

**Date: November 10, 2021
Person Contacted: Robert J. Willoughby (A&P)
NTSB Accident Number: WPR21LA194**

Narrative:

The following is a synopsis of the information provided by Mr. Willoughby in an e-mail correspondence.

On or about October of 2008, Mr. Willoughby repaired the fuel distributor assembly in accordance Teledyne Continental fuel injection manual guidelines and current service bulletins. Assembly tested and found to perform within manufacturers specifications.