



Bear Lake County Sheriff

Incident #: 21-B0826

Reporting Officer: Gregg Knutti

Report Time: 05/29/2021 12:54:44

Incident

Incident Nature
Traffic Accident

Address
BEAR LAKE COUNTY
AIRPORT

Occurred From
05/29/2021 12:52:30

Occurred To
05/29/2021 12:52:30

Received By
Paul Christiansen

How Received
Telephone

Contact

Disposition
Default from CAD (temp)

Miscellaneous Entry

Disposition Date
05/29/2021

Cleared

Judicial Status

Cleared Date

Clearance
Report to Follow

STOUT, TREVOR L

Complainant

Address
[REDACTED]
GENESEE ID 83832 8733

Phone
() -

DOB
[REDACTED]

Sex
M

Race
White/Non Hispanic

Responding Officer(s)

Gregg Knutti

Austin Budge

Ryan Larsen

Paul Christiansen

Offenses

Traffic Accident, Prop Damage

Statute

Description

Category

Persons

FLIGHT STANDARDS DISTRICT OFFICES Contacted

Address	Phone	DOB
Boise Idaho 83705		
Race	Sex	Ethnicity
Height	Weight	
	0	

ELDREDGE, TODD C PILOT

Address	Phone	DOB
Draper Utah 84020		
Race	Sex	Ethnicity
White/Non Hispanic	M	
Height	Weight	

ELDREDGE, HEIDI A Passenger Unit #1

Address	Phone	DOB
Draper Utah 84020	() -	
Race	Sex	Ethnicity
White/Non Hispanic	F	
Height	Weight	

STOUT, TREVOR L Complainant

Address	Phone	DOB
GENESEE Idaho 83832 8733	() -	
Race	Sex	Ethnicity
White/Non Hispanic	M	
Height	Weight	

Narratives

Original Narrative**05/30/2021 17:25:07**

On 05-29-2021, at 1254 hours a aircraft crash was reported at the Bear Lake County Airport. When I arrived at the airport I followed the airport manager to the east end of the main runway. At the east end of the runway there was a single engine airplane tail number N6334P lying upright in the grass and in about 2 inches of water. The pilot and a female passenger was being helped from the aircraft both walked to another airport vehicle.

The pilot's name is Todd Eldredge DOB [REDACTED], Address [REDACTED], Draper Utah, the passenger was the pilot's wife Heidi Eldredge DOB [REDACTED]

The pilot said they were flying to Jackson Wyoming, he was at 11,500 feet near a mountain peak by Montpelier when the aircraft loss power. He turned toward the airport, as he was approaching the east end of the main runway, he did not have enough altitude to make it to the runway. The plane touched down on the east side of the road that runs on the east side of the airport. The aircraft's right wing hit a fence post which took off part of the wing. The plane then hit the roadbed the front landing gear was broken off and was lying on the east edge of the road and the pitot tube was lying in the middle of the road. The left wing landing gear was also broken off and was lying in the ditch on the west side of the road. The plane then went over the airport fence and came to rest upright in the grass at the end of the runway.

The pilot and passenger were transported by ambulance to the Bear Lake Memorial Hospital in Montpelier.

Photograph's were taken at the scene, the landing gear was removed from the road the airport manager has those items.