



Photo 1 – View of airplane skin damage to lower fuselage (photo courtesy of the local fixed based operation)