




Photo 1 – View of damage to the floatplane’s tail section (Courtesy of FAA)