



Photo 1 – View of left side of airplane (photo courtesy of the pilot)



Photo 2 - View of right side of airplane (photo courtesy of the pilot)



Photo 3 - View of empennage damage (photo courtesy of the pilot)



Photo 4 - View of nose gear hydraulic flex line (photo courtesy of the NTSB)