



Photo 1 – Photo of N3965S at the accident site. Photo courtesy of the pilot.



Photo 2 – Lower section of the nose gear upper torque link. Photo courtesy of the pilot.



Photo 3 – Upper section of the nose gear upper torque link. Photo courtesy of the pilot.