



Memorandum for Record

Eric M. Gutierrez
Air Safety Investigator
National Transportation Safety Board
Investigator in Charge

NTSB Accident Number: WPR22FA001
Aircraft Registration & Make/Model: N412TL, Robinson, R22
Accident Location: Chandler, Arizona
Accident Date: October 1, 2021

An autopsy of the student pilot was performed by the Maricopa County Office of the Medical Examiner in Phoenix, Arizona. The cause of death was multiple blunt injuries.