

Joshua Cawthra

From: Kyle Garner
Sent: Thursday, October 12, 2023 6:42 AM
To: Joshua Cawthra
Subject: WPR22FA216 - email report - GoPro
Attachments: WPR22FA216_1.jpg; WPR22FA216_2.jpg; WPR22FA216_3.jpg; WPR22FA216_4.jpg

Email report instructions:

The narrative and attachments from this email report may be used in other reports at the discretion of the IIC. This email, including attachments (if applicable), should also be placed in the public docket by the IIC.

Email report contents:

The Vehicle Recorder Division received a GoPro camera (model and serial number unknown). The device arrived exhibiting signs of severe thermal damage (see WPR22FA216_1.jpg and WPR22FA216_2.jpg). The internal memory component of the device, a microSD card, was removed and inspected under a microscope. The microSD card also had severe thermal damage (see WPR22FA216_3.jpg and WPR22FA216_4.jpg). An attempt to communicate with the microSD card via a lab PC was unsuccessful. There are no known recovery methods for this type of damage.

Due to the severity of the damage, no data were able to be recovered from the device.

Prepared by:

Kyle Garner, Sr. Aerospace Engineer (Recorder Specialist), NTSB RE-40