

Joshua Cawthra

From: Garner Kyle
Sent: Monday, October 31, 2022 7:23 AM
To: Cawthra Joshua
Subject: WPR22FA256 - Gold Hill, CO - GoPro Email Report
Attachments: WPR22FA256_GoPro_1.jpg; WPR22FA256_SD_front.jpg; WPR22FA256_SD_back.jpg

Hi Josh,

See email report below.

Thanks,
Kyle

Email report instructions:

The narrative and attachments from this email report may be used in other reports at the discretion of the IIC. This email, including attachments (if applicable), should also be placed in the public docket by the IIC.

Email report contents:

The Vehicle Recorder Division received a GoPro camera (model and serial number unknown). The device arrived exhibiting signs of severe thermal and impact damage (see WPR22FA256_GoPro_1.jpg). The internal memory component of the device, a microSD card, was removed and inspected under a microscope. The microSD card also had severe thermal damage (see WPR22FA256_SD_front.jpg and WPR22FA256_SD_back.jpg).

Due to the severity of the damage, no data were able to be recovered from the device.

Prepared by:

Kyle Garner, Aerospace Engineer (Recorder Specialist), NTSB RE-40