

NAME/
SIGNATURELICENCE:
AME or
AMO/ACA

Date: 08/30/2021 Hours: 5471

Tail#: N926LL

Make: Textron (Cessna)

Model: 180H

S/N: 180-51470

Repaired outboard left wing, wing tip and outer skin on left door post area. in accordance with Cessna 100 series service manual. See 337. Installed STC SA4179NM and STC SA2918NM P Ponk gear casting, support brackets and angles. Gear legs were rectified by AIX LLC. Installed new wheel half, Cessna step, constructed new brake lines, new seat rails as required by AD 11-10-09. Repaired and reskined elevator and aileron. Installed Tail Cone Kit per AD20-21-22 and inspected tail cone per AD. Replaced fuel line under floor left tank. Reskined both flaps due to fatigue cracks. Replaced top and center rudder bearings. Installed STC SA1120SE AP enterprises door stewards and STC SA01636SE ABI Baby Bushwheel. Installed new left fuel cell. Performed annual inspection - see AD list. Painted to match existing scheme. I certify that this aircraft has been inspected in accordance with an annual inspection and is approved for return to service.

NEW ELT BATTERY Exp 7/2026 - Tested, per 91.207(d) - found good

Name: Tom Farrell

Co: Farrell Aircraft

Sign

10/07/2021 N926LL SN: 18051470 Tach:5485.5 Aligned main gear axle spindles. Installed customer supplied new ABI-1010 1.25/1.5 Wheels with new 8.5-10 6 ply tires and tubes per STC SA01765SE. Installed new ABI 30-52N brake calipers L/R. Reinstalled left tailwheel cable onto pulley. Checked elevator and stabilizer control movement - customer given discrepancy list.

--- Roger Charles Anderson ---