

From: [REDACTED]
To: [REDACTED]
Subject: Re: WPR22LA040 Boulder City, NV-N5057S
Date: Wednesday, December 15, 2021 10:29:56 AM
Attachments: [image001.png](#)

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

I replied to your Kiteworks message, but perhaps that didn't come through....

According to the Part Catalog (p/n 753-582) the bolt which attaches the rod to the landing gear door should be an AN3C10A with a length of 1-1/32".

The bolt which attaches the rod to the landing gear should be an AN3CH7A with a length of 29/32".

I don't know the answer to the question of bolt vs hydraulics.

Let me see what I can find out.



Jonathon Hirsch | Air Safety Investigator
jon.hirsch@piper.com | www.piper.com
p: [REDACTED]
[REDACTED]

This email is intended only for the use of the individual or entity to which it is addressed. It may contain information that is attorney client privileged, confidential, and/or proprietary. If you have received this email in error, please (1) do not use this information in any way; (2) notify the sender by reply e-mail; (3) and immediately delete this message and any of its attachments.