



Photo 1 – Right main landing gear door rod-end bolt. (Photo courtesy of a hired mechanic)



Photo 2 - Left main landing gear door rod-end bolt. (Photo courtesy of a hired mechanic)



Photo 3 - Right main landing gear door rod-end bolt. (Photo courtesy of the NTSB-IIC)



Photo 4 – Mechanical damage inside of right main landing gear wheel well. (Courtesy of the insurance adjuster)