

From: [REDACTED]
To: [REDACTED]
Subject: Re: [External]N7592Y question?
Date: Thursday, February 3, 2022 1:10:40 PM
Attachments: [image001.png](#)

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Hi Eric,

I have spoken with all the current CFI's and a couple former CFI's who have given flight training in N7592Y. None of them report any unusually hard landings in the aircraft. This aircraft has always been flown dual or with an examiner on board and I am unaware of any landings being reported as hard landings. I also looked through the squawk sheets and maintenance logs and found no mention of hard landings.

Thanks,
Marshall

From: Gutierrez Eric [REDACTED]
Sent: Tuesday, February 1, 2022 10:12 AM
To: Collins, Marshall [REDACTED]
Subject: [External]N7592Y question?

Hello Marshall,

Prior to the accident flight in N7592Y, where there any reports of any hard landings? Metallurgical examination of the fracture surfaces on the pivot assembly revealed that it had fractured due to overstress.

Respectfully,

Eric



Eric M. Gutierrez
Air Safety Investigator
National Transportation Safety Board
32125 32nd Avenue South, Suite 140
Federal Way, WA 98001
Office – 253-835-5382
Fax - 202-640-2972
[REDACTED]