

Date	Propeller TSN TSO	A/C Hours	Description of Work			
10/2			1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number: 125612
10/4			4. Organization Name and Address: MAXWELL AIRCRAFT SERVICE, INC.			5. Work Order/Contract/Invoice Number: 125612
10/5			6. Item:	7. Description:	8. Part Number:	9. Quantity:
10/6			1	M.T. PROPELLER	MTV-9-D/210-58	1
10/7						10. Serial Number: 150716
10/8						11. Status/Work: REPAIRED
10/9			12. Remarks: INSPECTED AND REPAIRED PROPELLER ONLY AS NEEDED (LEAKING GREASE AT BLADE SEALS) IN ACCORDANCE WITH M.T. PROPELLER MANUALS E-220 REVISION 66, E-808 REVISION 13, E-1290 REVISION 45. *****NOTE: WORK PERFORMED ON THIS REPAIR ORDER CANNOT BE CONSIDERED AN OVERHAUL*****			
10/10			13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
10/11			13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
10/12						
10/13			13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed): CONRAD E. MAXWELL	14e. Date (dd/mm/yyyy):
10/14			User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.			
10/15			FAA Form 8130-3 (02-14)			

Date	Propeller TSN TSO	A/C Hours	Description of Work																		
			1. Approving Civil Aviation Authority/Country: United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number: 21-50469															
			4. Organization Name and Address: Rocky Mountain Propellers, Inc.			5. Work Order/Contract/Invoice Number: 21-50469															
			6. Item:	7. Description:	8. Part Number:	9. Quantity:															
			1	MT Propeller	MTV-9-D / 210-58	1															
						10. Serial Number: 150716															
						11. Status/Work: Overhauled															
			12. Remarks: Overhauled propeller in reference to MT Service Manual # 61-12-20 [E-220], Rev. 65, and other supporting documents. Complied with Service Letters thru #65, Rev. 1 and Service Bulletins thru 32. No AD's currently apply. Next Overhaul Due: 2400 hours, or 72 calendar months, whichever occurs first. <table border="0"> <tr> <td>Propeller</td> <td>TSN</td> <td>TSO</td> </tr> <tr> <td>Hub S/N - 150716</td> <td>1966.42</td> <td>0.00</td> </tr> <tr> <td>Blade # 1 - AGF-57705</td> <td>1966.42</td> <td>0.00</td> </tr> <tr> <td>Blade # 2 - AGF-57706</td> <td>1966.42</td> <td>0.00</td> </tr> <tr> <td>Blade # 3 - AGF-57707</td> <td>1966.42</td> <td>0.00</td> </tr> </table>				Propeller	TSN	TSO	Hub S/N - 150716	1966.42	0.00	Blade # 1 - AGF-57705	1966.42	0.00	Blade # 2 - AGF-57706	1966.42	0.00	Blade # 3 - AGF-57707	1966.42	0.00
Propeller	TSN	TSO																			
Hub S/N - 150716	1966.42	0.00																			
Blade # 1 - AGF-57705	1966.42	0.00																			
Blade # 2 - AGF-57706	1966.42	0.00																			
Blade # 3 - AGF-57707	1966.42	0.00																			
			A complete description of work performed is on file at the above referenced organization under the work order and system tracking reference number indicated in blocks 3 and 5. Notice: An Airworthiness Directive may apply to the article(s) described hereon. The installer is responsible for ensuring complete compliance with any applicable Airworthiness Directives. "Certifies that the work specified in block 11 / 12 was carried out in accordance with FAR Part-145 and EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Approval Number: EASA.145.4827"																		
			13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.																
			13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:															
			13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy): 02 Sep 2021															
			User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.																		

[illegible]