




Photo 1 – View for forward fuselage undercarriage damage (photo courtesy of the owner)