



Eric M. Gutierrez
Air Safety Investigator
Western Pacific Region

Date: June 24, 2022

Subject: WPRLA217, Record of Conversation

Contact: Paul A. Pia, Aviation Safety Inspector, Federal Aviation Administration

Examination of N61KT, Cub Crafters, CC19-215 at the McCall Municipal Airport (MYL), McCall, Idaho, revealed substantial damage to the left wing and left elevator consistent with a ground loop. The brake line near the left main landing gear brake caliper was separated. The brake caliper, brake line, and fitting were removed and sent to the NTSB for additional examination.