

Eric M. Gutierrez
Air Safety Investigator
Western Pacific Region

Date: August 8, 2022

Subject: WPR22LA246, Memorandum for Record

Contact: Wreckage Recovery Company, Air Transport

The wreckage recovery company reported that, upon arrival at the accident location of N7609X, the airplane's engine and various instruments were missing.



Figure 1: View of accident airplane (Photo courtesy of recovery company)



Figure 2: View of accident airplane missing various instruments (Photo courtesy of recovery company)