



Investigator Name: Albert Nixon
Title: Senior Aviation Accident Investigator
Division: Aviation Safety - WPR

Date: August 11, 2022

Subject: WPR22LA301 Memorandum for Record - Record of Email

Contact: Eric Gutierrez - NTSB Duty Officer

- The following is a summary of the email:
- The pilot of N5780F reported that during take off roll the airplane was not performing as expected.
- During the initial climb, the engine rpm dropped.