



Photo 1 – N242BH, bottom view. Photo courtesy of Cal-Fire.



Photo 2 – Top view. Photo courtesy of Cal-Fire.



Photo 3 – Tail rotor drive shaft. Photo courtesy of Cal-Fire.



Photo 4. Air conditioning pulley with tail rotor drive shaft attachment flange. Photo courtesy of Cal-Fire



Photo 5 – Air conditioning pulley with bolt and nuts trapped in the holes. Photo courtesy of Cal-Fire.