

AIRCRAFT DESCRIPTION

Registration No. N 814WT

Model: PA-34-220T Popular Name: SENECAV

Serial No.: 3449495 Type Certificate No.: A7SO

Colors: MATTE HORN WHITE / BLACK PEARL & BEIGE MET. / BLACK PEARL

Engine Manufacturer: CONTINENTAL Serial Numbers: Single

Original Engine Model: TSIO-360-RB5B Left 1009899

LTSIO-360-RB5B Right 1009984

Propeller Manufacturer: MCCAULEY Hub or Serial Number: Single

Original Propeller Model: 3AF32C522 Left 130979

3AF32CS23 Right 140024

Blade Numbers

Left	Right
<u>AHJ26191</u>	<u>AIA31001</u>
<u>AHJ26193</u>	<u>AIA31003</u>
<u>AHJ26194</u>	<u>AIA31004</u>

2015 MODEL

AIRCRAFT LOG

The Flight Shop, Inc. 435-723-3469 N814WT Hobbs 455.0 4/28/2021
A/C TT 455.0 LH & RH Engine 455.0 TSN LH & RH Prop 455.0 TSN
Airframe

1. Replaced ELT battery April 2028, ELT test per FAR 91-207(D);
2. Replaced seal on both fuel screens; 3. Serviced A/C battery; 4. Lubed gears;
5. CW AD2005-13-16 nose gear cleanliness; 6. CW AD2020-24-09 Rudder cables; 7. CW AD2004-25-16 heater valves; 8. No ICA's.

I certify that this airframe has been inspected in accordance with an annual inspection and found to be in airworthy condition.

AP [REDACTED] IA
License Number

[REDACTED]
Craig Hulse

The Flight Shop, Inc. 435/723-3469 N814WT 4/29/2022 Hobbs 483.2
A/C TT 483.2 LH & RH Engine 483.2 TSN LH & RH Prop 483.2 TSN

1. Rotated both main tires; 2. Serviced batteries; 3. CW AD's 2005-13-16 nose gear cleanliness, 2020-24-09 rudder control cables, 2022-03-15 Garmin fuel indicators, 2004-21-05 heater pressure test, 2004-25-16 heater fuel valve; 4. No ICA's due.

I certify that this airframe has been inspected in accordance with an annual inspection and found to be in an airworthy condition.

AP [REDACTED] IA
License Number

[REDACTED]
Craig Hulse

Service Information

Consult the Continental Motors web site at continentalmotors.aero for engine related news or announcements. Continental Motors Internet Service contains useful information for Continental Motors engine owners, including electronic versions of the most current engine Instructions for Continued Airworthiness and service bulletins that may be pertinent to your engine model.

If internet access is not available, contact our Customer Service Department at:
1-888-826-5465 Toll free in the United States or
1-251-438-8299 International

Engine Returns

Return engines for core credit with this log book to:

Continental Motors, Inc.
2039 Broad Street
Mobile, AL 36615 USA

Return engines for overhaul with this log book to:

Mattituck Services
410 Airway Drive
Mattituck, NY 11952 USA

**USE ONLY FUEL CONFORMING TO ASTM D910
USE OF AUTOMOTIVE FUEL IS PROHIBITED**



If a **Continental Motors, Inc.** in this

location, this log book is **Production Certificate 508** of the original. Consult

the original engine log book for engine history and information recorded

Printed:

2/26/2014

Test Date:

2/25/2014

This engine model TSI0360RB5B , serial number 1009899
was manufactured by Continental Motors in accordance with
approved design data and the applicable requirements of Part 21 of
the Federal Aviation Regulation. The approved design data for this
engine incorporates all changes required by applicable Airworthiness
Directives and Continental Motors Service Bulletins.

[Redacted signature]

Date

Carried for

The Flight Shop, Inc. 435/723-3469 N814WT 7/9/2020 Hobbs 397.1
LH Engine Log
1. Replaced all rocker cover gaskets with 'Real Gaskets' RG632310 12ea.

AP [redacted] A
License Number

[redacted]
Craig Hulse

Cord
al and
ectives,

The Flight Shop, Inc./435-723-3469 N814WT Hobbs 455.0 4/28/2021
LH Engine

1. Changed engine oil, serviced with Phillips 20x50; 2. Changed oil filter; 3. Serviced spark plugs.

I certify that this engine has been inspected in accordance with an annual inspection and found to be in airworthy condition.

AP [redacted] A
License Number

[redacted]
Craig Hulse

The Flight Shop, Inc. 435/723-3469 N814WT 4/29/2022 Hobbs 483.2
LH Engine 483.2 TSN

1. Changed engine oil, serviced with Philips 20w50; 2. Changed engine oil filter, opened old, no contamination found; 3. Lubed wastegate; 4. Ground run engine satisfactory.

I certify that this engine has been inspected in accordance with an annual inspection and found to be in an airworthy condition.

AP [redacted] IA
License Number

[redacted]
Craig Hulse

PROPELLER ASSEMBLY LOG

PAGE NUMBER

LH Prop

1. Dressed, painted, and lubed prop; 2. Checked operation of deice boots.

Signature &
Certificate
Number

I certify that this prop has been inspected in accordance with an annual inspection and found to be in airworthy condition.

AP [REDACTED] LA
License Number

Craig Hulse

The Flight Shop, Inc. 435/723-3469 N814WT 4/29/2022 Hobbs 483.2
LH Prop 483.2 TSN

1. Dressed, lubed, and painted prop; 5. Checked condition and operation of de-ice boots.

I certify that this prop has been inspected in accordance with an annual inspection and found to be in an airworthy condition.

AP [REDACTED] A
License Number

Craig Hulse

PROPELLER ASSEMBLY LOG

PAGE NUMBER

Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
------	------------	---------------------	--------------------------------------	-----------------------------	--------------------------------

Signature &
Certificate
Number

MCGAULEY PROPELLER SYSTEMS
STANDARD LIMITED WARRANTY

McCAULEY



MCCALEY

STANDARD LIMITED WARRANTY

McCauley Propeller Systems, A Division of The Cessna Aircraft Company, Wichita, Kansas, U.S.A., expressly warrants new and remanufactured products produced and sold by McCauley to be free from defects in material and workmanship under normal use and service for a period of thirty-six (36) months after delivery to the original retail purchaser or until the expiration of the maximum hours of use or calendar limits for overhaul published by McCauley for the subject product, whichever occurs first.

McCauley's obligation under this limited warranty is limited to repairing or replacing, at its sole option, any propeller, propeller parts, governor or governor parts determined to be defective and which are properly returned by the owner, with a written statement describing the alleged defect and Service Center authorized to service the individual McCauley product. The repair charge to the owner for parts, or labor for removal and installation, except export/import duties and/or sales or replacement of defective propellers, is applicable warranty period of the original part. This limited

BLADE LOG

BLADE LOG



PROPELLER

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

PROP MODEL (R)
3AF32C523
PROP S/N (R) 140024
REG NO N814WT
WORK ORDER P3319



Repair Station No. K5SR339N
303 N 2370 W
Salt Lake City, Utah 84116
Phone: 801-933-7500

DATE 3/28/2019
A/C TSN 328
PROP TT (R) 328
TSPOH (R)
HOBBS 328

Date

Right Prop Entries

(10) RIGHT PROPELLER HAS BEEN INSPECTED FOR A 100 HOUR INSPECTION PER FAR 43 APPENDIX D USING THE PA34-220T INSPECTION CHECKLIST 05-20-00 AS A REFERENCE AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED AT THIS DATE AND TIME.

I certify the airframe, engine and/or component identified herein was repaired and inspected in accordance with the current Keystone Aviation LLC Repair Manual System and the Federal Aviation Regulations under which the operator is certified, and was determined to be in an Airworthy Condition at this date and time with regards to the inspection(s) and/or maintenance performed, and is approved for return to service as per those requirements. Pertinent details of the repair are on file under Work order No. P3319

DATE: 3/28/2019

SIGNED: _____

Work Order: P3319

Bruce Tanis
Certified Repair Station No. K5SR339N

Printed by EBis 3 (datamedia.com)

Signature &
Certificate
Number

The Flight Shop, Inc. 435/723-3469 N814WT 4/16/2020 Hobbs 375.2
RH Propeller Log

1. Dressed and painted prop; 2. Checked condition and operation of de-ice boots; 3. Sent prop governor for reseal/repair; 4. Ground run, ops check satisfactory.

I certify that this prop has been inspected in accordance with an annual inspection and found to be in an airworthy condition.

AP _____ IA
License Number

Craig Hulse

PROPELLER ASSEMBLY LOG

PAGE NUMBER _____

The Flight Shop, Inc./435-723-3469 N814WT Hobbs 455.0 4/28/2021
RH Prop

1. Dressed, painted, and lubed prop; 2. Checked operation of deice boots.

Date

I certify that this prop has been inspected in accordance with an annual inspection and found to be in airworthy condition.

Signature &
Certificate
Number

AP _____ IA
License Number

Craig Hulse

The Flight Shop, Inc. 435/723-3469 N814WT 4/29/2022 Hobbs 483.2
RH Prop 483.2 TSN

1. Dressed, lubed, and painted prop; 2. Checked condition and operation of de-ice boots.

I certify that this prop has been inspected in accordance with an annual inspection and found to be in an airworthy condition.

AP _____ A
License Number

Craig Hulse

BLADE LOG

Service Information

Consult the Continental Motors web site at continentalmotors.com for engine related news or announcements. Continental Motors Internet Service contains useful information for Continental Motors engine owners, including electronic versions of the most current engine Instructions for Continued Airworthiness and service documents that may be pertinent to your engine model.

If Internet access is not available, contact our Customer Service Department at:
1-888-826-5465 Toll free in the United States or
1-251-436-8299 International

Engine Returns

Return engines for core credit with this log book to:

Continental Motors, Inc.
2039 Broad Street
Mobile, AL 36615 USA

Return engines for overhaul with this log book to:

Continental Motors, Inc.
Factory Service Center
8600 County Road 32
Fairhope, Alabama 36532 USA

**USE ONLY FUEL SPECIFIED IN OPERATOR'S
MANUAL OR TYPE CERTIFICATE DATA SHEET
USE OF AUTOMOTIVE FUEL IS PROHIBITED**



Continental Motors, Inc.

Production Certificate 508

Printed: 3/12/2014

Test Date: 3/11/2014

This engine model LTSI0360RB5B, serial number 1009984 was manufactured by Continental Motors in accordance with approved design data and the applicable requirements of Part 21 of the Federal Aviation Regulation. The approved design data for this engine incorporates all changes required by applicable Airworthiness Directives and Continental Motors Service Bulletins.

[Redacted signature]

	Total Time	Time Since Last Overhaul

Time Since Last Overhaul

 D_i^{k+1}

oval and
Directives,

Carried

I certify that this engine has been inspected in accordance with an annual inspection and found to be in an airworthy condition.

Craig Hulse