

ROTAX.

ENGINE LOG BOOK

NO.:

LS-099-0422

FOR ROTAX 2-STROKE AND 4-STROKE AIRCRAFT ENGINES
EDITION: 2020 07 01 | PART NO.: 898023


A BRP BRAND




Table of Contents

Base record.....	2
Engine installation record.....	3
SB-status and modification record.....	5
Modification record.....	6
Maintenance record.....	7
Some advice for record keeping of an engine log book.....	42

Base record:

Engine log book number: LS-099-0422		for piston engine
Type of engine: 915	Model: 153 A	Engine serial no.: 9133788
Manufacturer: BRP-Rotax GmbH & Co KG, 4623 Günskirchen, Austria		Year of manufacture: NOV. 2021
Data sheet: P.S. ASTA F2339-190		
Take off power: 105,00 kW	perm. duration: 5 min	at 5800 r.p.m.
Max. cont. power: 99,00 kW	at 5500 r.p.m.	
Note: The above mentioned engine is considered to be operationally reliable if operated and maintained in accordance with the Civil Aircraft and Civil Aviation Equipment Order, current issue and the pertinent operational and maintenance instructions.		
Remarks: CONFIGURAZIONE STANDARD		
Date: 13 APR. 2022		Signature: LUCIANO SORBA  RIV. (BS) 00274 00980

Engine installation record:

Aircraft:		Date:		Engine hours:		Signature & Licence no.:
Registr.:	type:	in:	out:	TSN	TSO	
N-2442	RISE SV			0	/	

Engine installation record:

Aircraft:		Date:		Engine hours:		Signature & Licence no.:
Registr.:	type:	in:	out:	TSN	TSO	
						VZ-2442 SV

Maintenance record:

[illegible]

Maintenance record:

[illegible]

ROTAX.

Engine serial no.

Type of aircraft

Aircraft registration no.



Gedruckt nach der Richtlinie des
Österreichischen Umweltzeichens
„Druckerzeugnisse“,
Steuer Medienhaus GmbH, UW-Nr. 1175

Rotax® authorized distributor

FLYROTAX.COM

® and TM are trademarks of BRP-Rotax GmbH & Co KG. © 2020 BRP-Rotax GmbH & Co KG. All rights reserved.

