



Record of Conversation

Dan Baker
Senior Air Safety Investigator
Western Pacific Region

Date: 03/02/2023
Subject: WPR23LA013, Pilot Interview
Person Interviewed: Robert Snow

Mr. Snow was the pilot of a Piper PA30, N7746Y, when it was involved in an accident at Ryan Airfield, Tucson, AZ, on 10/15/2022.

Mr. Snow said he thought he heard an engine surge and the airplane yawed hard right when the airplane was on short final. He said he looked at the turn and slip indicator and the ball was full left and he used full left rudder to keep the airplane straight. The airplane wobbled a little bit, and then landed hard. When asked if he felt any unusual resistance in any of the engine controls prior to the accident he stated no, there was no unusual resistance.