



Photo 1 – photo of substantial damage to vertical stabilizer (photo courtesy of pilot)