



Kristyn Blocher  
Air Safety Investigator  
Western Pacific Region

**Date:** 10/26/2022

**Subject:** WPR23LA026

**Contact:** David Duncan, FAA

Per the phone conversation with David Duncan: the pilot stated that he had failed to plan his fuel appropriately and ran out of fuel short of his destination (S50). He is a first time airplane owner. He had very recently purchased the airplane.