



FIGURE 1 - TAIL ROTOR DRIVE SHAFT DAMAGE



FIGURE 2 - VERTICAL FIN DAMAGE