



Photo 1 – View from left side (Photo courtesy of Yuma Sheriff's Office)



Photo 2 – View of accident site (Photo courtesy of operator)



Photo 3 – View of tail rotor shaft rotor blade strike



Photo 4 – View of engine prior to removal



Photo 5 – Fuel nozzle removed at time of engine removal



Photo 6 – Engine prep for shipment to test facility



Photo 7 – Engine in test facility



Photo 8 – View of rotor mast at shear point



Photo 9 – View of rotor yoke at shear point



Photo 10 – Left side view of helicopter in storage at operator