



Photo 1 – View of substantial damage to vertical stabilizer and rudder (courtesy of pilot)



Photo 2 – View of substantial damage to right wing (courtesy of pilot)