



Photo 1 – View of substantial damage to fuselage (courtesy of pilot)



Photo 2 – View of substantial damage to horizontal stabilizer (courtesy of pilot)