



Photo 1 – View of substantial damage to vertical stabilizer and rudder (courtesy of pilot)