

Scott Johnson
Air Safety Investigator
Western Pacific Region

Date: 04/10/2023

Subject: 6120 Mechanical Malfunction/Failure Clarification / WPR23LA146

Contact: Alex Asp, CFI OC flight lessons

The following is a synopsis of the information provided by Mr. Asp in a telephone conversation.

Alex responded to the question, Was there Mechanical Malfunction/Failure? Alex responded, "Yes, flight control failure". He clarified this that it was subsequent to the accident. Or after encountering the wake turbulence of the 737, after the airplane came to a stop.

According to the pilot there were no preimpact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

Total time: 891

Make and Model: 891