

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Morgan State: Utah

ZIP: 84050 Country: Morgan county

Latitude: 41.008125 Longitude: -111.680740

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 04/08/2023 Local Time: 19:37

mm/dd/yyyy

Time Zone: Mountain

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N17NK

Manufacturer: Vans

Model: RV-7

Serial Number: 73089

Year of Manufacture: 2021

Amateur-Built: ☒ Yes ☐ No If Yes: ☒ Kit/Plans ☐ Original Design Make: Vans

☐ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 1800 lbs

Weight at Time of Accident/Incident: 1447 lbs

Number of Seats: 2 Flight Crew Seats: 1

Cabin Crew Seats: 1 Passenger Seats: 1

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☒ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle ☒ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☐ Carburetor ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	<u>Titan</u>	<u>IOX-370-A4D3T8</u>	<u>F3E002</u>	<u>06/06/2016</u>	<u>187</u>	<u>136</u>	<u>3</u>	<u>136</u>
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☒ Conditional Inspection
☐ Annual ☐ Unknown

Date Last Inspection: 04/01/2023

mm/dd/yyyy

Airframe Total Time: 133.95 hrs

hours measured at (Select one)

- ☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☒ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Hand held fire ext.

Propeller 1

- ☐ Fixed Pitch
☒ Controllable Pitch
☐ Ground Adjustable

Manufacturer: MT

Model: MTV-12-B

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ACK

Model or Part No.: E-04 ELT

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
☐ Airframe Parachute
☒ Angle of Attack Indicator
☒ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Kelly C StevensCity: Salt Lake CityState: UTZIP: 84109Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: US**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)

Airport Name: _____

Distance From Airport Center: _____ sm

Airport Identifier: _____

Direction From Airport: _____ degrees true

Proximity to Airport: ☐ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/A

Airport Elevation: _____ ft. msl

Runway Information

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Kelly City of Residence: Salt Lake City
 Middle Initial: C State: UT ZIP: 84109
 Last Name: Stevens Country: US
 Age at time of Accident/Incident: 62 Date of Birth: 1960 mm/dd/yyyy
 Certificate Number:

Degree of Injury ☐ None ☐ Fatal ☒ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☒ 4-point</td> <td>☒ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☒ 4-point	☒ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☐ 3-point	☐ 3-point																
☒ 4-point	☒ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☒ Commercial ☐ US Military ☐ Private ☐ Recreational ☒ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer		Medical Certificate ☐ None ☐ Class 3 ☒ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown															
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown		Medical Certificate Validity ☒ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance															
Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>12/08/2023</u> mm/dd/yyyy		Flight Review Aircraft Make: <u>Canadair</u> Model: <u>CL-65</u>															

Medical Certificate Limitations

Medical Certificate Special Issuance

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
Type Ratings <u>EMB-120 CL-65</u>			Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	20,000	145		17,000						
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days	15	3		12						
Last 30 Days	10	3		7						
Last 24 Hours	0			0						

Degree of Injury ☐ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type Available ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer			

Principal Occupation	Medical Certificate	Medical Certificate Validity	Date of Last Medical
☐ Pilot ☐ Other ☐ Unknown	☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	☐ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance	<i>mm/dd/yyyy</i>

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: _____ <i>mm/dd/yyyy</i>	Flight Review Aircraft Make: _____ Model: _____
---	--

Airplane Rating(s) (Check all that apply)	Other Aircraft Rating(s) (Check all that apply)	Instrument Rating(s) (Check all that apply)	Instructor Rating(s) (Check all that apply)
☐ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	☐ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport

Type Ratings	Student Endorsements <i>(Include dates)</i>
---------------------	--

[illegible]

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KBTF</u> City: <u>Woods Cross</u> State: <u>Utah</u> Country: _____	Time of Departure Time: <u>19:16</u> Time Zone: <u>Mountain</u>	Destination Airport ID: <u>KBTF</u> City: <u>Woods Cross</u> State: <u>Utah</u> Country: _____	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
--	--	---	---

Type of ATC Clearance/Service (Check all that apply)

☒ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☐ Class D ☒ Class E	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: <u>9000</u> ft msl
---	--	---	---	--

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather	☐ Company ☐ Military ☐ Internet ☐ None ☐ Unknown
--	---

Weather Observation Facility

Facility ID: _____
 Observation Time: _____
 Time Zone: _____
 Distance from Accident Site: _____ nm
 Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

_____ ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: _____ (C) or 65 (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
or _____ MB

Wind Direction

☒ Variable

-or-
Direction: _____ degrees true

Wind Speed

☒ Calm
☐ Light and Variable

-or-
Speed: _____ kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility unlimited miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☒ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property (Use additional sheet if necessary)

Description of damage to Aircraft and other property

Aircraft, damaged significantly, flipped upon touchdown in approximately 24 inches of snow. Nose damaged, front Cowl damaged, tail, both vertical stabilizer and horizontal stabilizer's, and elevators, heavily damaged when tail impacted the ground during the rollover. Fuselage rippled forward of tail. Canopy broken during egress. Propeller missing.

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

On April 8, 2023 at approximately 1910 local time, I performed an engine start in KBTF with the intent on going for a short local flight. The aircraft had recently come out of conditional inspection and had been operated approximately 3 hrs and 07 minutes.

Those hours were composed of three separate flights, as well as a 45 minute engine run on the ground.

After a preflight in the hangar, an uneventful engine start, engine run up, taxi out and pre takeoff checks, I departed KBTF at approximately 19:17 local. I departed northbound on runway 35, turning eastbound after departure. I continued a climb as I turned northbound along the foothills. Climbing to approximately 9000 feet as I turned eastbound through Farmington Canyon to cross the Wasatch range into the Morgan Valley south of Morgan, Utah.

I believe that I was still eastbound when I noticed what seemed to be an unusual oil burning smell when I opened up the heater. I quickly turned that off and opened up the air vents, subsequently checking the CO2 numbers that my headset monitors, which showed zero ppm. I turned around and started heading back towards the pass at the top of Farmington canyon to return to KBTF with the option of potentially diverting to the slightly closer 42U (Morgan county airport). I checked the distance to KBTF on my avionics which showed 15.9 nautical miles direct. I could see its approximate location, north of my location, to my right and roughly 12 miles distant, 42U, which is north and west of the town of Morgan. I was south of the town of Morgan approximately 8-10 miles.

A short time later, a minute perhaps, I felt some light but not normal vibration in the airframe, uncertain of the origin, I believe that I reached for the propeller control to adjust the speed of the engine and propeller to see if the vibration changed or not? As I touched that control, there was a shudder in the airframe and immediately the windscreen was covered in oil, and I could no longer see forward. All power from the engine was gone. I immediately started making turns both left and right, as I slowed to best glide speed, searching for a suitable place to land. I was at 9000 feet initially when this happened and was quickly losing altitude. I looked to the north and judged 42U far too distant, there were more and more buildings and structures becoming more congested the farther north you went towards the town of Morgan and further northwest towards the airport. I did not believe I could make that airport with the remaining altitude that I had. So I stayed in the vicinity where I was in the south end of Morgan Valley and continued to look for an suitable landing option. I was on Unicom, 122.8 from KBTF, which was also the same frequency for 42U (Morgan County Airport). I didn't know what the ATC center frequency was, and didn't think I was high enough to get reception at that altitude, nor did I have the available time to find the frequency. So I broadcasted blindly on Unicom and another aircraft near Logan, Utah answered my transmission. I let them know that I had an engine failure and was landing south of Morgan, they said they would get in contact with ATC, that was our last transmission.

During this approximately four minute time frame descending for eventual landing, i was very task saturated with the selection of location and forthcoming landing with limited visibility. I did not look over engine instruments at all, other than to monitor airspeed. There was a Road on each side of the valley going approximately north and south, and I started looking at those, I was still high enough that I could not tell how clear the roads were of power poles, power-lines, fences and other obstacles. There were fields between the two roads that I was looking at as well, however they were all snow covered. Descending lower, I committed to the road, on the east side of the valley. I was headed southbound looking at that road on my left, with the field on my right. The road had too many power-lines and too many obstructions, so I turned a right base and then final, to the field, continuing my decent northbound. I had zero forward visibility but could see a fence going to the left and to the right that I was quickly approaching, I touched down (the last speed I saw on my airspeed just before touchdown was 53kts) with little distance remaining before that fence on the main landing gear, immediately the airplane flipped as the main gear sunk into the snow that was about 24" deep.

I was upside down in my seat belt, but felt uninjured despite being shaken up. I released the seat belt and freed myself of my upside down state. I turned off the battery master and the main fuel valve. I then put my back against one side of the interior and tried to kick the plexiglass canopy with both feet hard enough to break it. No luck. Fuel started dripping, not aggressively, but nevertheless fuel on the inside of a closed upside down airplane. I reached back and unhooked the fire extinguisher. I saw my phone, and dialed my sister. I

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

a through and consistent engine inspection plan in place for young engines.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Titan IOX-370-A4D3T8 S/N F3E002 engine failure and separation of the MT propeller MTV-12-B S/N 170647.

**Total Time/Cycles
On Part**136.3 Hours

Cycles

**Time Since This Part
Inspected/Overhauled**136.3 Hours**FUEL & SERVICES INFORMATION****Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

33 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT**Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Upside down aircraft holding holding canopy closed. Used fire extinguisher to break opening in canopy.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number****Manufacturer:** _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

04/17/2023

mm/dd/yyyy

Name of Pilot/Operator: Kelly C Stevens

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR23LA149

Reviewed by NTSB Regional Office

OAS-WPR

Name of Investigator

Kathryn Whitaker

Date Report Received

January 14, 2025

Narrative History of Flight (Copied from NTSB 6120)

On April 8, 2023 at approximately 1910 local time, I performed an engine start in KBTF with the intent on going for a short local flight. The aircraft had recently come out of conditional inspection and had been operated approximately 3 hrs and 07 minutes.

Those hours were composed of three separate flights, as well as a 45 minute engine run on the ground.

After a preflight in the hangar, an uneventful engine start, engine run up, taxi out and pre takeoff checks, I departed KBTF at approximately 19:17 local. I departed northbound on runway 35, turning eastbound after departure. I continued a climb as I turned northbound along the foothills. Climbing to approximately 9000 feet as I turned eastbound through Farmington Canyon to cross the Wasatch range into the Morgan Valley south of Morgan, Utah.

I believe that I was still eastbound when I noticed what seemed to be an unusual oil burning smell when I opened up the heater. I quickly turned that off and opened up the air vents, subsequently checking the CO2 numbers that my headset monitors, which showed zero ppm. I turned around and started heading back towards the pass at the top of Farmington canyon to return to KBTF with the option of potentially diverting to the slightly closer 42U (Morgan county airport). I checked the distance to KBTF on my avionics which showed 15.9 nautical miles direct. I could see its approximate location, north of my location, to my right and roughly 12 miles distant, 42U, which is north and west of the town of Morgan. I was south of the town of Morgan approximately 8-10 miles.

A short time later, a minute perhaps, I felt some light but not normal vibration in the airframe, uncertain of the origin, I believe that I reached for the propeller control to adjust the speed of the engine and propeller to see if the vibration changed or not? As I touched that control, there was a shudder in the airframe and immediately the windscreen was covered in oil, and I could no longer see forward. All power from the engine was gone. I immediately started making turns both left and right, as I slowed to best glide speed, searching for a suitable place to land. I was at 9000 feet initially when this happened and was quickly losing altitude. I looked to the north and judged 42U far too distant, there were more and more buildings and structures becoming more congested the farther north you went towards the town of Morgan and further northwest towards the airport. I did not believe I could make that airport with the remaining altitude that I had. So I stayed in the vicinity where I was in the south end of Morgan Valley and continued to look for an suitable landing option. I was on Unicom, 122.8 from KBTF, which was also the same frequency for 42U (Morgan County Airport). I didn't know what the ATC center frequency was, and didn't think I was high enough to get reception at that altitude, nor did I have the available time to find the frequency. So I broadcasted blindly on Unicom and another aircraft near Logan, Utah answered my transmission. I let them know that I had an engine failure and was landing south of Morgan, they said they would get in contact with ATC, that was our last transmission.

During this approximately four minute time frame descending for eventual landing, i was very task saturated with the selection of location and forthcoming landing with limited visibility. I did not look over engine instruments at all, other than to monitor airspeed. There was a Road on each side of the valley going approximately north and south, and I started looking at those, I was still high enough that I could not tell how clear the roads were of power poles, power-lines,

fences and other obstacles. There were fields between the two roads that I was looking at as well, however they were all snow covered. Descending lower, I committed to the road, on the east side of the valley. I was headed southbound looking at that road on my left, with the field on my right. The road had too many power-lines and too many obstructions, so I turned a right base and then final, to the field, continuing my decent northbound. I had zero forward visibility but could see a fence going to the left and to the right that I was quickly approaching, I touched down (the last speed I saw on my airspeed just before touchdown was 53kts) with little distance remaining before that fence on the main landing gear, immediately the airplane flipped as the main gear sunk into the snow that was about 24" deep.

I was upside down in my seat belt, but felt uninjured despite being shaken up. I released the seat belt and freed myself of my upside down state. I turned off the battery master and the main fuel valve. I then put my back against one side of the interior and tried to kick the plexiglass canopy with both feet hard enough to break it. No luck. Fuel started dripping, not aggressively, but nevertheless fuel on the inside of a closed upside down airplane. I reached back and unhooked the fire extinguisher. I saw my phone, and dialed my sister, I shared my location with her and had her call emergency services and hung up. I used the fire extinguisher as a battering implement against the plexiglass canopy, which successfully created an opening to extricate myself from the airplane. As I was extracting myself from the canopy, someone arrived and he gave me a hand finishing my egress. Crash fire rescue arrived soon there after. I was examined and released by the ambulance crew, with a small scrape and bump on the head and some scratch's. My sister retrieved me soon there after.