

N60372

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 11469.6

DATE: 9/24/2021
WORK ORDER:
Eng. TSO 2245.5

LOG ENTRY

Installed a new Michelin Condor 6.00 X 6 left main tire (P/N 072-314-0). Re-greased wheel bearings.

SIGNATURE: Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 11545.6

DATE: 10/30/2021
WORK ORDER:
Eng. TSO 2321.5

LOG ENTRY

Installed a new left door window spring (P/N 0711021-9). Installed 1 forward cowling receptacle (P/N S2319-50). Operation tested satisfactorily.

SIGNATURE: Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 11570.2

DATE: 11/5/2021
WORK ORDER:
Eng. TSO 2346.1

LOG ENTRY

Installed a new Whelen beacon lamp assembly (P/N02-0350433-01). Operation tested satisfactorily.

SIGNATURE: Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 11587.6

DATE: 11/12/2021
WORK ORDER:
Eng. TSO 2363.5

LOG ENTRY

Installed new right and left Rapco brake linings (4 each P/N RA66-10500). Operation tested satisfactorily.

SIGNATURE: Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 11610.6

DATE: 11/24/2021
WORK ORDER:
Eng. TSO 2386.5

LOG ENTRY

Installed new Lamar alternator solenoid (P/N X61-0029). Installed a serviceable Lamar ACU (P/N AC2101; S/N T63223). Inspected alternator field lead. Ground ran and operation tested satisfactorily.

SIGNATURE: Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 11,659.1

DATE: 12/14/2021
WORK ORDER:
Eng. TSOI 2435.0

LOG ENTRY

Installed a new Donaldson induction air filter (P/N P819281). This constitutes compliance with AD #84-26-02 (Dated 1/29/1985). Next due 12,159.1 tach time. Installed 1 new Skybolt cowl mount (P/N SK2003-42A) in the lower left position.

SIGNATURE: Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

N60372REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **11660.1**DATE: **12/22/2021**
WORK ORDER:
Eng. TSOI **2436.0****LOG ENTRY**

Removed failed GDU1040 from the MFD position and transferred the PFD unit to the MFD position. Installed an overhauled GDU (P/N 011-00972-03; S/N 88902850) into the PFD position (See Garmin International FAA form 8130 number 15719957). Performed configuration procedure I.A.W. Cessna Service Bulletin SEB-34-03. Operation tested good.

SIGNATURE: _____

CERTIFICATE NUMBER: _____

REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **11678.3**DATE: **1/8/2022**
WORK ORDER:
Eng. TSOI **2454.2****LOG ENTRY**

Installed 4 new cowling fastener receptacles (P/N S2310-50) on the forward upper cowling edge. Operation tested good.

SIGNATURE: _____

CERTIFICATE NUMBER: _____

*Kelly M Yates*REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **11771.8**DATE: **1/31/2022**
WORK ORDER:
Eng. TSOI **2547.7****LOG ENTRY**

Installed new right Condor 6.00 X 6 main tire (P/N 072-314-0). Installed a new Airstop inner tube (P/N 092-500-0) on the left main.

SIGNATURE: _____

CERTIFICATE NUMBER: _____

*Kelly M Yates*REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **11801.5**DATE: **2/9/2022**
WORK ORDER:
TTAF: **11801.5**
Eng. TSOH: **2577.4****LOG ENTRY**

Installed 3 new cowling fastener receivers (P/N S2319-50) on the upper, forward cowl edge. Operation tested satisfactorily.

SIGNATURE: _____

CERTIFICATE NUMBER: _____

*Kelly M Yates*REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **11836.4**DATE: **2/19/2022**
WORK ORDER:
TTAF: **11836.4**
Eng. TSOH: **2612.3****LOG ENTRY**

Installed a new left wing Aeroflash strobe power supply (P/N 153-0008). Operation tested satisfactorily.

SIGNATURE: _____

CERTIFICATE NUMBER: _____

*Kelly M Yates***AIRFRAME**

N60372REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12073.2**DATE: **4/23/2022**
WORK ORDER:
TTAF: **12073.2**
Eng. TSOH: **2849.1****LOG ENTRY**

Installed a new nose wheel tire (P/N 072-312-0) and inner tube (P/N 097-908-0). Cleaned and greased nose wheel bearings.

SIGNATURE: **Kelly M Yates**

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12098.5**DATE: **5/6/2022**
WORK ORDER:
TTAF: **12098.5**
Eng. TSOH: **2874.4****LOG ENTRY**

Installed a used/serviceable alternator. Ground ran and operation tested satisfactorily.

SIGNATURE: **Kelly M Yates**

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12107.6**DATE: **5/9/2022**
WORK ORDER:
TTAF: **12107.6**
Eng. TSOH: **2883.5****LOG ENTRY**

Installed a new left main Condor 6.00 X 6 tire (P/N 072-314-0). Installed 2 new left caliper brake linings (P/N RA66-10500). Operation tested satisfactorily.

SIGNATURE: **Kelly M Yates**

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: **N60372**
MODEL: **C172-S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12156.2**DATE: **6/9/2022**
WORK ORDER:
TTAF: **12156.2**
TSOH Eng: **2932.1****RECURRING AIRWORTHINESS DIRECTIVE STATUS**

AD#	84-26-02 Dated 1/29/1995	SUBJECT	PAPER AIR FILTERS	INTERVAL	Every 500 Hours	DUE TACH	12656.2
AD#	2013-11-11 Dated 05/01/2013	SUBJECT	OIL PRESSURE SWITCHES	INTERVAL	Every 3000 Hours	DUE TACH	15033.4
AD#	2015-19-07 Dated 11/03/2015	SUBJECT	FUEL INJECTION LINES	INTERVAL	Every 110 Hours	DUE TACH	12266.2

LOG ENTRY

Inspected battery. Serviced tires. Greased all wheel bearings. Installed new right and left brake linings (P/N RA066-10500). Lubricated all flight control hinges, pulleys, and bellcranks. Serviced brake reservoirs. Lubricated cabin climate controls. Fit, installed, and painted McFarlane dorsal fin fairing (P/N SA 0531012-2). Made minor repair to the left rear headphone jack plug mount. Tightened right and left forward fuselage side steps. Installed 2 new left door latch springs (P/N 0717026-3). Operation tested and checked ELT per F.A.R. 91.207d. Batteries due 2/2025. Complied with AD 84-26-02 (Dated 1/29/85) by installing a new Donaldson induction air filter (P/N P198281). Complied with AD 2015-19-07 (Dated 11/03/2015) by visual inspection. Verified compliance with all applicable ADs through 2022-11. Ground ran and operation tested satisfactorily. I certify that this **AIRCRAFT** has been inspected in accordance with an **Annual Inspection** and was found to be in an airworthy condition.

SIGNATURE: **Kelly M Yates**

CERTIFICATE NUMBER: [REDACTED]

AIRFRAME

N60372

Flite Instruments and Avionics

4927 E. Falcon Drive

Mesa, AZ 85215

CRS# 6FIR926C

480-516-0308

Reg #	A/C Make	Model	S/N	Tach/Hobb
60372	Cessna	172c	172S10216	6069

I certify that the Static, Altimeter and transponder tests, including data correspondence required by 91.411 & 91.413, have been performed and found to comply with 14 CFR part 43, appendix E & F.

Work performed by: [REDACTED]

Date: 06/09/2022

Inspected by: [REDACTED]

Work Order#

60372

REG. NO.: N60372

Engine: IO-360-L2A

DATE: 7/8/2022

MODEL: C172S

S/N: L-30517-51A

WORK ORDER:

S/N: 172S10216

Tach: 12207.5

Eng. TSOI 2983.4

LOG ENTRY

Installed new Knots2U rudder lower end cap (P/N K0533155-1).

SIGNATURE: [REDACTED]

CERTIFICATE NUMBER: [REDACTED]

Kelly M Yates

REG. NO.: N60372

Engine: IO-360-L2A

DATE: 8/9/2022

MODEL: C172S

S/N: L-30517-51A

WORK ORDER:

S/N: 172S10216

Tach: 12256.4

Eng. TSOI 3032.3

LOG ENTRY

Serviced, charged, and installed new Gill G243 battery (S/N 03155938). Installed new right and left wingtip Whelen LED anti-collision light assemblies (P/N 01-0771994-00). Ground ran and operation tested satisfactorily.

SIGNATURE: [REDACTED]

CERTIFICATE NUMBER: [REDACTED]

Kelly M Yates

REG. NO.: N60372

Engine: IO-360-L2A

DATE: 8/27/2022

MODEL: C172S

S/N: L-30517-51A

WORK ORDER:

S/N: 172S10216

Tach: 12293.6

Eng. TSOI 3069.5

LOG ENTRY

Installed a new left main tire (P/N 072-314-0). Installed a new Rosen left side sun visor (P/N RCS-200-1). Ground ran and operation tested satisfactorily.

SIGNATURE: [REDACTED]

CERTIFICATE NUMBER: [REDACTED]

Kelly M Yates

REG. NO.: N60372

Engine: IO-360-L2A

DATE: 9/1/2022

MODEL: C172S

S/N: L-30517-51A

WORK ORDER:

S/N: 172S10216

Tach: 12306.4

Eng. TSOI 3082.3

LOG ENTRY

Re-sealed nose strut assembly with new O-rings (1 each MS28775-228 & -329) and serviced with 5606 fluid and nitrogen.

SIGNATURE: [REDACTED]

CERTIFICATE NUMBER: [REDACTED]

Kelly M Yates

AIRFRAME

N60372REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12307.2**DATE: **9/19/2022**
WORK ORDER:
Eng. TSOI: **3083.1****LOG ENTRY****Removed engine for overhaul.**

SIGNATURE: [REDACTED]

Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-29721-51A**
Tach: **12307.2**DATE: **9/25/2022**
WORK ORDER:
Eng. TSOH: **0.0****LOG ENTRY**

Installed overhauled engine S/N L-29721-51A (See Aircraft Engine Specialists work order number E5857-22-03) with 4 new engine mounts (2 each P/N J-9613-49 & -72) and a new oil pressure switch (P/N 83278). Installed new AWI muffler (P/N A1754001-23; S/N 228372) and shroud (P/N A9954100-3; S/N 233992) with serviceable exhaust risers. Installed pre-existing induction air filter and carried the time in service over in the aircraft logs. Re-installed existing/serviceable alternator, and vacuum pump. Made minor repairs to the engine cooling baffles. Installed a new pilot's seat height adjustment jack-screw rod (P/N 0514226-12) and block (P/N 0514037-3). Ground rap and leak checked satisfactorily.

SIGNATURE: [REDACTED]

Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12397.6**DATE: **10/18/2022**
WORK ORDER:
TTAF: **12397.6**
Eng. TSOH: **90.4****LOG ENTRY**

Installed a new left navigation light bulb (P/N WL-A-7512-24). Installed new right door spring door stop (P/N 0517023-1). Operation tested satisfactorily.

SIGNATURE: [REDACTED]

Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12414.5**DATE: **10/26/2022**
WORK ORDER:
TTAF: **12414.5**
Eng. TSOH: **107.3****LOG ENTRY**

Removed GMU-44 magnetometer (P/N 011-00870-00; S/N 47510507) for repair. Installed serviceable unit (P/N 011-00870-00; S/N 47525091) and downloaded appropriate software for installation. Operation tested satisfactorily.

SIGNATURE: [REDACTED]

Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12558.1**DATE: **12/14/2022**
WORK ORDER:
TTAF: **12558.1**
Eng. TSOH: **250.9****LOG ENTRY**

Installed a new Whelen beacon bulb assembly (P/N 02-0350433-01). Operation tested satisfactorily.

SIGNATURE: [REDACTED]

Kelly M Yates

CERTIFICATE NUMBER: [REDACTED]

N60372

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 12593.9

DATE: 12/26/2022
WORK ORDER:
TTAF: 12593.9
Eng. TSOH: 286.7

LOG ENTRY

Installed a new 5.00X5 nose tire (P/N 072-312-0) and inner tube assembly (P/N GL-5067B).
Operation tested satisfactorily.

SIGNATURE: [Redacted]
Kelly M Yates

CERTIFICATE NUMBER: [Redacted]

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 12654.4

DATE: 1/20/2023
WORK ORDER:
Eng. TSOI [Redacted]

LOG ENTRY

Installed a new Tempest induction air filter (P/N AA198281). This constitutes compliance with AD 84-26-02. Next due 13154.4 tach time.

SIGNATURE: [Redacted]
Kelly M Yates


CERTIFICATE NUMBER: [Redacted]

Chandler Avionics 1725 E. Ryan Rd. #8 Chandler, AZ 85286 Eric.S@ChandlerAvioincs.com

REG	MAKE/MODEL	SERIAL NUMBER	~~HOBBSTACH~~	DATE
N60372	CESSNA 172S	172S10216	5706.2	26 January 2023

Removed GMU 44 and replaced with newley overhauled SN 47518654. Performed software load.
Reinstalled and tested IAW Installation Manual. All work was accomplished with the manufacturer's most recent installation manual revision and AC 43.13-1B and 2B. No change to Electrical load analysis and Weight and Balance.

TECH [Redacted]
CERT [Redacted] ERIC DIRKSEN



REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 12692.3

DATE: 2/6/2023
WORK ORDER:
Eng. TSOI [Redacted]

LOG ENTRY

Installed a new left main Condor 6.00 X 6 tire (P/N 072-314-0) and inner tube (P/N GL-6020B). Installed new right and left brake linings (4 each. P/N 066-10500).

SIGNATURE: [Redacted]
Kelly M Yates

CERTIFICATE NUMBER: [Redacted]

REG. NO.: N60372
MODEL: C172S
S/N: 172S10216

Engine: IO-360-L2A
S/N: L-30517-51A
Tach: 12740.8

DATE: 2/27/2023
WORK ORDER:
TTAF: 12740.8
Eng. TSOH: 433.6

LOG ENTRY


Removed HID landing light assembly and power supply. Installed a Whelen Parmetheus LED landing light (P/N 01-0771833-20; S/N 830793). Checked right fuel quantity sender wiring. No defects noted. Operation tested both satisfactorily.

SIGNATURE: [Redacted]
Kelly M Yates



CERTIFICATE NUMBER: [Redacted]

N60372REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12760.2**DATE: **3/10/2023**
WORK ORDER:
TTAF: **12760.2**
Eng. TSOH: **453.0****LOG ENTRY**



Installed a new Leakguard 6.00 X 6 inner tube (P/N GL-6020B) in the right main tire.
Serviced and leak checked good.

SIGNATURE: 
Kelly M YatesCERTIFICATE NUMBER: REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12800.7**DATE: **3/21/2023**
WORK ORDER:
TTAF: **12800.7**
Eng. TSOH: **493.5****LOG ENTRY**


Installed a new Condor 6.00 X 6 right tire (P/N 072-314-0). Installed 3 new left lower cowl
mounts (P/N SK2003-42A). Operation tested good.

SIGNATURE: 
Kelly M YatesCERTIFICATE NUMBER: REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12829.3**DATE: **3/31/2023**
WORK ORDER:
TTAF: **12829.3**
Eng. TSOH: **522.1****LOG ENTRY**



Installed new pilot's seat adjustment and lock assembly (P/N SPL1925-1). Operation
tested good.

SIGNATURE: 
Kelly M YatesCERTIFICATE NUMBER: REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12840.8**DATE: **4/3/2023**
WORK ORDER:
TTAF: **12840.8**
Eng. TSOH: **533.6****LOG ENTRY**

Installed new vacuum transducer assembly (P/N P165-5786). Ground ran and operation
tested satisfactorily.

SIGNATURE: 
Kelly M YatesCERTIFICATE NUMBER: REG. NO.: **N60372**
MODEL: **C172S**
S/N: **172S10216**Engine: **IO-360-L2A**
S/N: **L-30517-51A**
Tach: **12905.3**DATE: **4/19/2023**
WORK ORDER:
TTAF: **12905.3**
Eng. TSOH: **598.1****LOG ENTRY**

Installed new Condor 6.00 X 6 left main tire (P/N 072-314-0). Installed new right and left
brake linings (4 each P/N RA66-010500).

SIGNATURE: 
Kelly M YatesCERTIFICATE NUMBER: **AIRFRAME**