



3147 Donald Douglas Loop S.
Santa Monica, CA 90405
310 397 8183

Invoice

Date	Invoice #
5/19/2023	4602

Bill To
Santa Monica Flyers
[REDACTED] S.

N#	Tach
819KS	65.8

Description	Rate	Amount
aircraft ran into fuel truck. carefully disentangled aircraft and towed to shop- 1.0 hour removed crew seats to inspect floorboards, landing gear legs, fixtures, and skins: no damage detected. removed wing root fairings to inspect wing attach points, spars, and wing struts. discovered RH strut slightly bowed, strut attach points look good. discovered upper and lower cowls damaged at nose bowl area and RH skin torn. replaced 10 shock mounts on cowl that were torn or stretched. discovered RH wing outboard leading edge and nose rib damaged. reinstalled all removed components and released for ferry flight- 10.0 hours 10% labor discount qty10 SK2003-42A mount 10% parts discount	[REDACTED]	[REDACTED]
Subtotal		[REDACTED]
Sales Tax (10.25%)		[REDACTED]
Payments/Credits		[REDACTED]
Balance Due		[REDACTED]

PLEASE NOTE: 4% surcharge of total will be applied to any credit card transaction