



Photo 1 – View of substantial damage to the right wing aileron N6174W (Courtesy of FAA)