

From: [Cornejo Tealeye](#)
To: [Rho Paul](#)
Subject: WPR23LA268 Keys 192586
Date: Monday, July 10, 2023 10:39:33 PM
Attachments: [image001.gif](#)

Good evening Paul,

I have attachments that I will send in separate emails.

FSDO (GEG - SPOKANE)

Tom Lang
[REDACTED]
[REDACTED]

He went on-scene and sent photos.

Spokane SO

Dep Ballou
[REDACTED]

Case # 2023-1100091

He reported it was very windy on-scene

Per the pilot:

He landed normally on runway 16. During the roll out, a gust of wind took the tail to the starboard side. He applied brakes to correct back to the runway; however, the airplane continued off the runway. The landing gear collapsed as the airplane departed the runway surface onto the dirt. the wing dragged on the ground and the came to rest in a nose down attitude.

Pilot reported no mechanical issues.

Regards,

Tealeye

Ms. Tealeye Cornejo
Air Safety Investigator
National Transportation Safety Board
Western Pacific Region
[REDACTED] [REDACTED] [REDACTED]
[REDACTED]
[REDACTED], [REDACTED]
[REDACTED]
[REDACTED]
Email: [REDACTED]