

ENGINE LOG

Serial No. L 28696

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature
	Hrs	Min		
4-6-'21	142	00	Exchanged engine oil (W15W-50) and filter, added 11oz Cam Guard	
4-8-21	142	22.2	Performed cylinder leakdown test and borescope inspection. Results satisfactory. #1 76/80 #2 74/80 #3 77/80 #4 73/80. Inspected engine IAW Lancair 235/320/360 Annual Type Inspection Checklist and found to be condition for safe operation.	
			Page Total	
			Brought Forward	
			Total to Date	

All Repair Data Must Bear t
Certificated Mechanic, and his Rating and
Certificate Number MUST be Shown.

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
	Tach				
12-18-21	197.3		Exchanged engine oil (W15W-50) and filter.		
	Hobbs 294.0				
1-4-22	295.00		One lead wire: broken contact; replaced all 8 leadwires with specified parts from Lightspeed Engineering		
	✓ Hobbs				
4-27-22	306.55		I certify that this engine has been inspected in accordance with the scope and detail of Appendix D to Part 43 and found to be in a condition for safe flight.		
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
10-7-22	Tach	244.6	Exchanged engine oil & filter 7qtrs W15W-50		
5-6-23	Tach	252.4	Upon recommendation of the electron		
	Hobbs	369.8	ignition system (light speed engineering)		
			exchanged all spark plugs from Denso		
			IK 24 to Denso IK27 (5312)		
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

ENGINE LOG

Serial No.

[illegible]