

NATIONAL TRANSPORTATION SAFETY BOARD

NTSB Form 6120.1

PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

Email the pilot/operator aircraft accident/incident report to the investigator-in-charge of your accident/incident. If email is not available, mail the report per the instructions below.

If your accident/incident occurred in Maine, Vermont, New Hampshire, Massachusetts, Connecticut, Rhode Island, New York, New Jersey, Pennsylvania, Maryland, Delaware, Virginia, West Virginia, Kentucky, Tennessee, North Carolina, South Carolina, Mississippi, Alabama, Georgia, Florida, the District of Columbia, Puerto Rico, or the US Virgin Islands, send the form to: NTSB, ERA, 45065 Riverside Parkway, Ashburn, VA 20147.

If your accident/incident occurred in Ohio, Michigan, Indiana, Wisconsin, Illinois, Minnesota, Iowa, Missouri, Arkansas, Louisiana, North Dakota, South Dakota, Nebraska, Kansas, Oklahoma, Texas, Colorado, or New Mexico, send the form to: NTSB, CEN, 4760 Oakland Street, Suite 500, Denver, CO 80239.

If your accident/incident occurred in Montana, Wyoming, Idaho, Utah, Arizona, Nevada, Washington, Oregon, California, Hawaii, or the territories of Guam or American Samoa, send the form to: NTSB, WPR, 505 South 336th Street, Suite 540, Federal Way, WA 98003.

If your accident/incident occurred in Alaska, send the form to: NTSB, ANC, 222 West 7th Avenue, Room 216, Box 11, Anchorage, AK 99513.

Rules pertaining to notification of aircraft accidents and incidents, as well as overdue aircraft are found in 49 *Code of Federal Regulations* (CFR) Part 830 http://www.ecfr.gov/cgi-bin/text-idx?c=ecfr&tpl=/ecfrbrowse/Title49/49cfr830_main_02.tpl. These rules state the authority of the NTSB, define accidents, incidents, injuries, and other terms, and provide procedures for initial and immediate notification of accidents and incidents by aircraft pilots/operators.

A. APPLICABILITY

The pilot/operator of an aircraft shall send a report to the office listed above, based on accident/incident location; immediate notification is required by 49 CFR 830.5(a). **The report shall be filed within 10 days after an accident for which notification is required by Section 830.5, or after 7 days if an overdue aircraft is still missing.**

An aircraft accident, as defined in 49 CFR 830.2, is determined as an occurrence that involves a fatality or serious injury, or substantial damage to the aircraft. For occurrences that do not involve a fatality, the determination that the occurrence is an accident can be appealed by writing to the Director, Office of Aviation Safety, NTSB, 490 L'Enfant Plaza, S.W., Washington, D.C. 20594.

INSTRUCTIONS TO PILOTS/OPERATORS FOR COMPLETING THIS FORM

It is necessary that ALL questions on this report be answered completely and accurately.

If more space is needed, continue on a blank sheet of paper.

Nearest City/Place: Use the name of the nearest community in the state where the accident/incident occurred. **Prescott, AZ**

Date/Time: Indicate the date and local time of the event. Be sure to indicate the time zone. **8:05am MST**

Phase of Operation: Indicate the phase of operation during which the accident/incident occurred. **Takeoff/Climb**

Aircraft Information: Enter aircraft make and model information as indicated on the aircraft registration certificate, including series. If the involved aircraft is certified as "amateur-built," include the name of the producer of the kit or plans, unless an NTSB employee instructs otherwise.

Maximum Gross Weight: Enter the certificated maximum gross weight for the aircraft involved in the occurrence. This should be the same as the maximum gross weight indicated on the aircraft weight and balance documents.

Engine: Enter engine make and model information as indicated on the engine data plate.

The NTSB uses this form for aircraft accident prevention activities and for statistical purposes. NTSB regulations (49 CFR Part 830) require that **ALL** questions be answered completely and accurately. Completion of this form will take approximately 60 minutes. The NTSB does not guarantee the privacy of any information provided in this form. You need not complete this form unless it displays a valid OMB control number, in accordance with 5 C.F.R. § 1320.5(b), which applies to this collection of information.

B. DEFINITIONS

1. "Aircraft Accident" means an occurrence associated with the operation of an aircraft that takes place between the time any person boards the aircraft with the intention of flight and all such persons have disembarked, and in which any person suffers death, or serious injury, or in which the aircraft receives substantial damage. For purposes of this form, the definition of "aircraft accident" includes "unmanned aircraft accident," as defined at 49 CFR 830.2.

2. "Substantial Damage" means damage or failure that adversely affects the structural strength, performance or flight characteristics of the aircraft, and that would normally require major repair or replacement of the affected component. NOTE: Engine failure or damage limited to an engine if only one engine fails or is damaged, bent fairing or cowlings, dented skin, small puncture holes in the skin or fabric, ground damage to rotor or propeller blades, and damage to landing gear, wheels, tires, flaps, engine accessories, brakes, or wing tips are not considered "substantial damage" for purposes of this report.

3. "Operator" means any person who causes or authorizes the operation of an aircraft, such as the owner, lessee, or bailee of an aircraft.

4. "Fatal Injury" means any injury that results in death within thirty (30) days of the accident.

5. "Serious Injury" means any injury that (1) requires hospitalization for more than 48 hours, commencing within 7 days from the date the injury was received; (2) results in a fracture of any bone (except simple fracture of fingers, toes, or nose); (3) causes severe hemorrhages, nerve, muscle, or tendon damage; (4) involves injury to any internal organ; or (5) involves second- or third-degree burns, or any burns affecting more than 5 percent of the body surface.

Type of Fire Extinguishing System: If a fire extinguishing system was used to fight an aircraft fire, specify the type(s) of extinguishing system(s) used. Examples include handheld extinguisher, engine fire bottle, cargo/baggage compartment fire suppression system, or airport emergency ground equipment.

Owner/Operator Information: Enter the owner information as shown on the registration certificate. Commercial operators, enter the operator information, including "doing business as" when applicable, as shown on the operator certificate.

Revenue Sightseeing Flight: Indicate whether the accident aircraft was conducting **revenue** sightseeing operations under 14 CFR Part 91 at the time of the accident.

Air Medical Flight: Indicate whether the accident flight was being conducted for the purpose of carrying medical personnel, patient(s), or organs.

Public Aircraft: Federal, state or local government flight operations such as official travel, law-enforcement, low-level observation, aerial application, firefighting, search and rescue, biological or geological resource management, or aeronautical research. Indicate whether the flight was conducted by the armed forces, federal, state, or local government.

Purpose of Flight: 14 CFR Parts 91, 103, 133, 136, and 137: Indicate the type of operation that was being conducted at the time of the occurrence using the following definitions:

AERIAL APPLICATION--Operations using an aircraft to perform aerial application or dispersion of any substance. Examples include agricultural, health, forestry, cloud seeding, firefighting, insect control, etc.

AERIAL OBSERVATION--These flights include aerial mapping/photography, patrol, search and rescue, hunting, highway traffic advisory, ranching, surveillance, oil and mineral exploration, criminal pursuit, fish spotting, etc.

AIR DROP--Aerial operations, other than aerial application, that are intended to release items in flight.

AIR RACE/SHOW--Includes any flight operations conducted as part of an organized air race or public demonstration.

BUSINESS--includes all personal flying without a paid professional crew for reasons associated with furthering a business, including transportation to and from business meetings or work. This does not include corporate/executive operations, air taxi, or commuter operations.

EXECUTIVE/CORPORATE--Company flying with a paid, professional crew.

FERRY--Non-revenue flight under a special flight or "ferry" permit. Refer to 14 CFR 21.197 for details of special flight permit issuance.

FLIGHT TEST--Flight for the purpose of investigating the flight characteristics of an aircraft/aircraft component or evaluating an applicant for a pilot certificate or rating.

INSTRUCTIONAL--Flying while under the supervision of a flight instructor or receiving air carrier training. Personal proficiency flight operations and personal flight reviews, as required by federal air regulations, are excluded.

OTHER WORK USE--Miscellaneous flight operations conducted for compensation or hire such as construction work (not 14 CFR Part 135 operation), parachuting, aerial advertising, towing gliders, etc.

PERSONAL--Flying for personal reasons (excludes business transportation) including pleasure or personal transportation. This also includes practice or proficiency flights performed under flight instructor supervision and not part of an approved flight training program.

POSITIONING--Non-revenue flight conducted for the primary purpose of relocating the aircraft. Examples include moving the aircraft to a maintenance facility or to load passengers or cargo etc.

UNKNOWN--Use only if the primary purpose of flight is not known.

Other Aircraft--Collision: For all accidents involving a collision with another aircraft, including parked aircraft, check "Collision with other aircraft" under Basic Information and complete this section indicating details about the OTHER aircraft involved in the collision.

Airport Information: Complete this section if the accident/incident occurred on approach, landing, takeoff, departure, or within 3 statute miles of an airport. Please refer to the FAA Airport/Facility Directory or other official source for airport information.

Airport Identifier: Provide the official 3 or 4 character airport identifier number. **KPRC**

Runway: Indicate the number of the runway used, including L, R, or C if applicable. **21L**

Runway/Landing Surface: Indicate the type of intended runway/landing surface (do not indicate surface conditions). If the surface type was mixed, check all that apply. **N/A**

Condition of Runway/Landing Surface: Indicate the condition of the intended runway/landing surface. If multiple conditions existed at the time of the accident, check all that apply. **N/A**

Weather Information at the Accident/Incident Site: Indicate the weather conditions reported at the accident/incident site at the time of occurrence. If no weather reporting was available for the accident/incident site, indicate the reported conditions at the nearest reporting site. Specify the weather reporting site identifier, the observation time, and distance from the accident/incident. **140 @ 5 Vis. 10SM BKN 050 T 19/16 A3027 DA 6000**

Sky/Lowest Cloud Condition: Indicate the height above ground level of the lowest cloud condition present at the time of the accident/incident and whether coverage was reported as few, scattered, broken or overcast. Also indicate the height above ground level and coverage of the lowest cloud ceiling present at the time of the accident/incident (reported as broken or overcast). **BKN 050**

NOTAMS (D and FDC), AIRMETs, SIGMETs, PIREPs: Describe all NOTAMS (distant (D) or Flight Data Center (FDC), if known), AIRMETs, SIGMETs, and PIREPs in effect near the accident/incident. **N/A**

Flight Crewmember Information: Indicate the category that best describes the capacity served by this flight crewmember at the time of the accident. The designators "Flight Crewmember 1" and "Flight Crewmember 2" do not refer to a specific pilot position or responsibility. If more than one pilot is aboard, they may be entered in any order and their capacity entered as appropriate. **PIC & SIC**

Degree of Injury: See Definitions on the top half of Page 1 of the instructions. Minor injury is not defined. If an injury does not meet the criteria for another injury category, select Minor. **N/A**

Date of Last Flight Review or Equivalent: Enter the date of the most recent flight review, or equivalent, completed by this pilot. Refer to 14 CFR 61.56 for accepted equivalents. **Ongoing commercial training**

Type Ratings: List all type ratings on the pilot certificate. If the pilot holds no type ratings indicate "none." If the pilot holds a pilot certificate other than student and was flying an aircraft requiring an endorsement, enter the type and date of any logbook endorsement(s) for that aircraft. See 14 CFR 61 for examples of required endorsements. **None**

Student Endorsements: If the pilot holds a student pilot certificate, enter all solo endorsements and dates on the student pilot certificate.

Flight Time: Complete the flight time matrix. Solo flight time should be included as "Pilot-in-Command (PIC)" and all dual flight instruction given should be included as "Time as Instructor."

Additional Flight Crewmembers: Complete this section if there were more than two required flight crewmembers on the aircraft. This also includes a check airman performing official duties but does not include cabin crew. State the capacity served by each included crewmember at the time of the accident.

Passenger(s)/Other Personnel: Enter identification and injury severity information for all passengers, cabin crew, and other personnel involved in the accident. See Page 1 of the instructions for the official definition of injury levels. **Claudio Copiano Jr. - Uninjured**

Armando Flores-Lindenfelser - Uninjured

Jena Hylton - Uninjured

Zoel Labelle - Uninjured

Several questions throughout the form allow for multiple responses; when appropriate, choose all responses that apply.

These instructions only pertain to major issue areas covered by NTSB Form 6120.1 Pilot/Operator Aircraft Accident/Incident Report. For additional definitions of questions and responses, please refer to www.ntsbgov.

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Prescott State: AZ

ZIP: _____ Country: USA

Latitude: _____ Longitude: _____

(Enter in decimal degrees or degrees minutes seconds)

Accident/Incident Date/Time

Date: 09/02/2023 Local Time: 8:06 AM

mm/dd/yyyy

Time Zone: MST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N6834W

Manufacturer: P per

Model: PA-28-140

Serial Number: 28-20975

Year of Manufacture: 1965

Amateur-Built: ☐ Yes ☒ No If Yes ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 2150 lbs

Weight at Time of Accident/Incident: 1990 lbs

Number of Seats: 4 Flight Crew Seats: 2

Cabin Crew Seats: 2 Passenger Seats: 2

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Restricted
☐ Aerobatic
☐ Limited
☐ Balloon
☐ Provisional
☐ Commuter
☐ Special Flight
☐ Transport
☐ Experimental
☐ Utility
☐ Special Light-Sport
☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)

☐ None

☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng 1	<u>Lycom ng</u>	<u>O-320-E2A</u>	<u>L-15193-27A</u>	<u>12/12/1983</u>	<u>150 @ 2700</u>	<u>1187.76</u>	<u>1164.79</u>	<u>1187.76</u>
Eng 2								
Eng 3								
Eng 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 05/31/2023
mm/dd/yyyy

Airframe Total Time: 3527.9 hrs

hours measured at (Select one)

☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Sensen ch

Model: M74DM-0-58

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes

ELT Manufacturer: ACK Techno og es Inc.

Model or Part No.: E-04-ELT

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated

Did ELT Aid in Locating Aircraft? ☒ Yes ☐ No

If not activated

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Armando Flores-LindenfelserCity: Junct onState: AZZIP: 85120Fractional Ownership Aircraft: ☐ Yes ☐ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☐ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Prescott Regional AirportDistance From Airport Center: 3NM smAirport Identifier: KPRCDirection From Airport: 200 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 5045 ft. msl**Runway Information**Runway ID: 21L (L/R/C) Length: 7619 ft Width: 150 ft**Runway/Landing Surface** (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☒ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sideslip ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

[illegible]

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

"Flight Crewmember 2" was pilot flying ☒ Yes ☐ No

First Name: Armando

City of Residence: Junction

Middle Initial:

State: **AZ** ZIP: **85120**

Last Name: Flores-Lindenfelser

Country: [USA](#)

Age at time of Accident/Incident: 29 Date of Birth: [REDACTED] 1993 mm/dd/yyyy

Certificate Number: [REDACTED]

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

☐ Left ☐ Front ☐ Unknown
☒ Right ☐ Rear
☐ Center ☐ Single

Available

☐ None
☒ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

☐ None
☒ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ None
 ☐ Flight Instructor
 ☐ Commercial
 ☐ US Military

☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign

☒ Student
 ☐ Sport
 ☐ Flight Engineer

☐ Pilot

☒ Other

☐ Unknown

☐ None
 ☐ Class 3
☒ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

☒ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

04/18/2023
mm/dd/yyyy

NDNE

Medical Certificate Special Issuance

**Date of Last Flight Review
or Equivalent, Including
FAR 121/135 Checks:**

mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model:

Airplane Rating(s)
(Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)
(Check all that apply)

☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)
(Check all that apply)

☒ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)
(Check all that apply)

☒ None
☐ Airplane Single-Engine
☐ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☐ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

Student Endorsements *(Include dates)*

[illegible]

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Restraint Type: Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Restraint Type: Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: <u>Claudio</u> City: <u>Miami</u> Middle Initial: _____ State: <u>FL</u> ZIP: <u>33187</u> Last Name: <u>Copiano Jr</u> Country: <u>USA</u> ☒ Crew ☐ Passenger ☐ Other			☒ Left ☐ Center ☐ Right ☐ Unknown Row: <u>1</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Armando</u> City: <u>Junction</u> Middle Initial: _____ State: <u>AZ</u> ZIP: <u>85120</u> Last Name: <u>lores-Linden elser</u> Country: <u>USA</u> ☒ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☒ Right ☐ Unknown Row: <u>1</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Jena</u> City: <u>Miami</u> Middle Initial: <u>Lynn</u> State: <u>FL</u> ZIP: <u>33187</u> Last Name: <u>Hylton</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☒ Left ☐ Center ☐ Right ☐ Unknown Row: <u>2</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Zoel</u> City: <u>Ottawa</u> Middle Initial: _____ State: <u>ON</u> ZIP: <u>K1J8E2</u> Last Name: <u>Labelle</u> Country: <u>Canada</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☒ Right ☐ Unknown Row: <u>2</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KPRC</u> City: <u>Prescott</u> State: <u>AZ</u> Country: <u>USA</u>	Time of Departure Time: <u>8:04AM</u> Time Zone: <u>MST</u>	Destination Airport ID: <u>KSEZ</u> City: <u>Sedona</u> State: <u>AZ</u> Country: <u>USA</u>	Type Flight Plan Filed ☐ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☒ VFR Activated? ☐ Yes ☒ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☒ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☒ Class D ☐ Class E	☐ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: _____ ft msl
---	---	---	---	--

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☒ Flight Service Station ☐ TV/Radio ☐ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather	☐ Company ☐ Military ☐ Internet ☐ None ☐ Unknown
--	---

Weather Observation Facility

Facility ID: _____
 Observation Time: _____
 Time Zone: _____
 Distance from Accident Site: 3 nm
 Direction from Accident Site: 200 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☒ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

5000 ft agl

Ceiling

☐ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☒ Unknown

Ceiling Height

_____ ft agl

Temperature: 19 (C) or _____ (F)

Dew Point: 16 (C) or _____ (F)

Altimeter Setting: 30.27 in. Hg
 or _____ MB

Wind Direction

☐ Variable

-or-
Direction: 140 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
Speed: 5 kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility 10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: 6000 ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

N/A

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☒ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Left wing tip struck a tree and spun, damaging the empennage and consequently the propeller.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

On the morning of September 2, 2023, at approximately 6:13 AM (local time), I, Claudio, along with Armando and our two passengers, Jena and Zoel, embarked on a flight from Falcon Field (KFFZ) to Prescott (KPRC). During the initial leg of the journey, I assumed control of the aircraft and carried out the necessary taxiing, takeoff procedures, and the subsequent flight segment. Weather conditions at the time were favorable, and we calculated our fuel requirements based on the current weight of the aircraft, ensuring that we departed from KFFZ with a sufficient 36 gallons of fuel on board, with plans to refuel upon reaching Prescott. Weight and balance, as well as performance calculations, were meticulously assessed before our departure, ensuring compliance with all relevant limits at both departure and arrival airports.

Our preflight checks were conducted thoroughly and yielded no concerns. Likewise, during the run-up, all systems were found to be functioning optimally. The flight to Prescott proceeded smoothly, and as we approached KPRC, Armando, who occupied the right seat, took control of the aircraft. He executed a 45-degree angle entry into the left downwind for runway 21L, executed a successful landing, and taxied the aircraft to the refueling area. Our time spent at the FBO in Prescott did not exceed 20 minutes, during which we requested only 10 gallons of fuel, corresponding to the amount consumed during the initial leg of the flight. Subsequent preflight checks were conducted without any deviations, with weight and balance remaining consistent. Performance calculations indicated a slightly extended takeoff roll, but it was well within the safe operating parameters, providing us with ample runway to execute a safe departure.

For the second leg of the flight, Armando once again assumed control, taxied to runway 21L, and conducted another run-up, all of which were completed satisfactorily. Following a short delay request, we were cleared for takeoff. Armando configured the aircraft with flaps set to 25, utilized the entire available runway, applied full power, and commenced the takeoff roll, which extended to approximately 3000 feet of runway. However, during the initial climb, I observed that the aircraft was not achieving the expected rate of ascent. Armando subsequently reported a drop in RPM, as the instrument panel was within his field of vision. Meanwhile, I focused on monitoring the other instruments on my side.

At an altitude gain of approximately 117 feet, it became evident that we were facing a critical situation, prompting preparations for an emergency landing. In response to Armando's struggle to gain altitude, I took control of the aircraft and endeavored to maximize airspeed without risking a stall. Recognizing the urgency of the situation, I issued instructions for everyone to prepare for impact and adjusted the aircraft's pitch to optimize glide distance while avoiding potential obstacles below. Simultaneously, Armando relayed our situation to air traffic control with the message, "We're going down," initiating emergency procedures.

Due to the elevated nose attitude, my forward visibility was limited, necessitating confirmation from Armando regarding the clearance on our right side, to which he confirmed the presence of a street with no vehicular traffic. With the utmost caution, we executed a controlled descent toward the street to facilitate a safe landing, diligently avoiding stalling or entering a spin. As we descended, the loss of power was accompanied by a pronounced noise and vibration from the aircraft, despite my noise-canceling headphones. Shortly thereafter, during our descent, the left wingtip made contact with a tree, resulting in a partial spin and culminating in an impact with the ground.

Immediately following the impact, I assessed the well-being of all occupants, and to my relief, they all confirmed their physical integrity. We promptly evacuated the aircraft, beginning with Armando, followed by the passengers seated in the rear, and concluding with my own exit. The time was approximately 8:06 AM.

RECOMMENDATION (How could this accident/incident have been prevented?)**Operator/Owner Safety Recommendation**

I believe that the aircraft had an engine failure right after takeoff since we began to lose power (RPM drop). Since the aircraft wasn't mine, I probably should've asked for more information about the aircraft's maintenance logs and requested information about who and where the last inspection was made. But it's tricky because according to the logs and documents, the aircraft was airworthy and I didn't notice any discrepancies or anything that made it unsafe to fly the aircraft.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Loss of power, RPM drop, possible engine failure.

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff
(Convert from pounds, as necessary)

36 Gallons

Fuel Type

☐ 80/87 ☐ 115/145 ☐ Jet B ☐ Other, specify _____
☒ 100 Low Lead ☐ Jet A ☐ JP8
☐ 100/130 ☐ Jet A-1 ☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFT

Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Flight crewmember 2 exited first, then the passengers from the back seats exited and flight crewmember 1 exited.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

N6834W

Manufacturer: P per

Model: PA-28-140

Damage to Other Aircraft

☐ Destroyed ☐ Minor
☐ Substantial ☐ None

Registered Owner of Other Aircraft

Name: Armando Flores-Lindenfelser

City: Juntion

State: AZ ZIP: 85120

Country: USA

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

09/10/2023

mm/dd/yyyy

Name of Pilot/Operator: Claudio Copiano Jr.

Signature: Claudio Copiano Jr.

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR23LA334

Reviewed by NTSB Regional Office

OAS WPR

Name of Investigator

S. B. Johnson

Date Report Received

9/23/2023