



Eleazar Nepomuceno
Aviation Accident Investigation
Western Pacific Region

Date: October 5, 2023

Subject: WPR23LA360, Phone interview

Contact: Vic Jaro, Twin Falls Fliers Inc., Director of Maintenance

In a phone interview with the Director of Maintenance, he verified that there was damage to N4757N's left lower fuselage and left side floor board, beneath the pedals.