

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	---

COMPONENT INSPECTION

I certify that these components have been inspected IAW Cameron Balloons US Annual Inspection procedures and were found to be airworthy and are released for service. Pertinent details are available on file at this agency.

Date 4/1/2023 Total Time Unknown

W/O# P232202 Signed [REDACTED] # [REDACTED]

AERCO 523 Rankin Rd NE Albuquerque, NM 87107 CRS RG1R451K
Division of Albuquerque Balloon Center Inc.

Cameron Balloons Standard cylinder P/N CB2901 S/N 00687: Installed new Pressure Relief Valve. Replaced fuel quantity gauge gasket. Performed Annual Inspection and **DOT External visual requalification (04-23E)**. The above cylinder was installed in N4961D. – END –

MAINTENANCE RELEASE

Mfgr. Balony Kubicek spol S.R.O. Model BB85Z

Part System S/N 851

The aircraft and/or component identified above was repaired and inspected IAW current Air Regulations and was found Airworthy for return to service. Pertinent details of this repair are on file at this agency under; W.O. # P232202

Date 4/1/2023 Signed [REDACTED] # [REDACTED]

AERCO 523 Rankin Rd NE Albuquerque, NM 87107 CRS RG1R451K
Division of Albuquerque Balloon Center Inc.