

AFC Aircraft WorksC/O Meridian
Hayward, CA 94545

Date: 8/3/2023

AIRCRAFT **N656TE** MAKE: **Superior Airparts** MODEL: **XPIO-360-B1A3**
S/N: **G06927** HOBBS: **818.2**

Drained and replenished engine oil Aeroshell 15W-50 8 quarts and 1 pint of AvBlend.
removed and replaced oil filter P/N Tempest AA48108-2. Examined old filter element, no
contaminates found. Removed and replaced 4 each valve cover gaskets P/N: 06B26669
Ran engine leak ck ok.

W. Fernandez

AFC Aircraft Works1
Hayward, CA 94545

Date: 7/2/2023

AIRCRAFT **N656TE** MAKE: **Superior Airparts** MODEL: **XPIO-360-B1A3**
S/N: **G06927** HOBBS: **768.2**

Drained and replenished engine oil Aeroshell 15W-50 8 quarts and 1 pint of AvBlend.
removed and replaced oil filter P/N Tempest AA48108-2. Examined old filter element, no
contaminates found. Repaired SCAT duct from the engine to the air/oil separator.
Ran engine leak ck ok.

W. Fernandez