

Kristyn Blocher
Air Safety Investigator
AS-WPR

Date: 4/16/24

Subject: WPR24FA124

Contact: Justin McConaughey, Advantage Jet Center; Maintenance

The following is a synopsis of an in person conversation with Mr. McConaughey, following the accident involving N965BC:

Mr. McConaughey stated that since the time that Advantage Jet Center had taken over the maintenance of N965BC, it had been very routine, overall. He mentioned one engine issue which had been dealt with recently. The chip detector warning light had illuminated in flight. The chip detector was checked, cleaned, and replaced. On the following flight, the chip detector warning light illuminated again, and the airplane was taken out of service while additional inspection and work was conducted on the engine. After the work was completed, the airplane was returned to service and to date, no additional problems had come up. The airplane had been returned to service about 25 flight hours prior to the accident, according to Mr. McConaughey.