

From: [Gerald Kawamoto](#)
To: [Andrew Swick](#)
Cc: [Christopher Babcock](#)
Subject: WPR24FA313 (Provo, Utah) Engine Data Monitor No Data Email Report
Date: Tuesday, November 12, 2024 9:34:48 AM
Attachments: [IMG_7655.jpg](#)
[IMG_7657.jpg](#)

Email Report Instructions:

The narrative and attachments from this email report may be used in other reports at the discretion of the IIC. This email, including attachments (if applicable), should also be placed in the docket by the IIC.

Email Report:

The Vehicle Recorder Division received an Insight GEM 610C (P/N: 610C-001, S/N: 1426). The device sustained impact damage during the accident event (IMG_7655.jpg, IMG_7657.jpg) and an SD card was not installed in the device or recovered with the wreckage, therefore, no data were recovered.

Prepared by:

Gerald Kawamoto, Recorder Specialist NTSB RE-40



Insight
Instrument Corp.

GRAPHIC ENGINE MONITOR

P/N: 6100-001 WT: 0.5 lb

S/N: 1426 TSC-0137

Power: 2 W Max/ 1 W Cont.

Voltage: 10 to 30 VDC

Mod: A B C D E F G H J K

Software Version: 1 2 3 4 5

Rev: 0 1 2 3 4 5 6 7 8 9

Rev: 0 1 2 3 4 5 6 7 8 9

DO-178B SOFTWARE LEVEL C

DO-178B Inv. Cat.

BABSUXXXXXXXZBBBCCTBA

MADE IN CANADA