



Invoice  
**WO\_372**  
Date: November 17, 2023  
Work completed: November 17, 2023  
Evaluate aircraft damage

**Evergreen Airworks LLC**

[Redacted Address]

**AIRCRAFT**

**N734LJ**

CESSNA 172N S/N: 17268935  
TACH: 4509.9

**BILL TO**

**James Mitchell**

[Redacted Address]

| Item                 | Discrepancy                                                                                                                                                                                                                                                                                             | Parts  | Labor    | Misc      |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------|-----------|
| 1.                   | Evaluate aircraft damage<br>Corrective Action                                                                                                                                                                                                                                                           | \$0.00 | \$217.50 | \$0.00    |
| 1-1                  | Evaluated aircraft damage and inventoried items of repair needed from a surface inspection. see claimant statement of loss dated November 17, 2023.<br><br>-- labor: 1.5 hrs @ \$145.00T                                                                                                                |        |          |           |
| 2.                   | Brake condition<br>Corrective Action                                                                                                                                                                                                                                                                    | \$0.00 | \$0.00   | \$0.00    |
| 2-1                  | Brake discs and linings measured - above (within) manufacturers limits of wear. Checked brake calipers and lines for evidence of leakage - none found. Measured fluid within master cylinders. Left was low, right was full. Both brakes felt firm and responsive with the rudder pedals. See pictures. |        |          |           |
| 3.                   | Aircraft Damage 1: New Propeller Required                                                                                                                                                                                                                                                               | \$0.00 | \$0.00   | \$0.00    |
| 4.                   | Aircraft Damage 2: Remove and Send engine for Inspect, Repair as Necessary (IRAN) inspection, and prop strike AD compliance<br><i>Remarks: Engine shop to perform and provide quote (15-30K). No accessory or external system refurbishments quoted here.</i>                                           | \$0.00 | \$0.00   | \$0.00    |
| 5.                   | Aircraft Damage 3: Replace engine muffler                                                                                                                                                                                                                                                               | \$0.00 | \$0.00   | \$0.00    |
| 6.                   | Aircraft Damage 4: Lower cowl sheet metal repair, remove dents                                                                                                                                                                                                                                          | \$0.00 | \$0.00   | \$0.00    |
| 7.                   | Aircraft Damage 5: Perform Upper cowl nose bowl fiberglass repair                                                                                                                                                                                                                                       | \$0.00 | \$0.00   | \$0.00    |
| 8.                   | Aircraft Damage 6: Rear left window broken out - replace                                                                                                                                                                                                                                                | \$0.00 | \$0.00   | \$0.00    |
| 9.                   | Aircraft Damage 7: Both cabin doors cracked in lower forward edges, stop drill and repair cracks                                                                                                                                                                                                        | \$0.00 | \$0.00   | \$0.00    |
| 10.                  | Aircraft Damage 8: Replace Comm 1 antennae                                                                                                                                                                                                                                                              | \$0.00 | \$0.00   | \$0.00    |
| 11.                  | Aircraft Damage 9: Remove Dent in empennage                                                                                                                                                                                                                                                             | \$0.00 | \$0.00   | \$0.00    |
| 12.                  | Aircraft Damage 10: Lower rudder hinge is bent/cracked skin                                                                                                                                                                                                                                             | \$0.00 | \$0.00   | \$0.00    |
| 13.                  | Aircraft Damage 11: Replace stressed and stretched rudder cables                                                                                                                                                                                                                                        | \$0.00 | \$0.00   | \$0.00    |
| 14.                  | Aircraft Damage 12: Remove and inspect RH wing flap jackscrew                                                                                                                                                                                                                                           | \$0.00 | \$0.00   | \$0.00    |
| 15.                  | Aircraft Damage 13: Replace Left flap for bent spar, skin and arms<br><i>Remarks: Airframe Components or Beegles Aircraft Repair Quote to get</i>                                                                                                                                                       | \$0.00 | \$0.00   | \$0.00    |
| 16.                  | Aircraft Damage 14: Left Wing Flap tracks bent, upper skin inbd area near rear spar damaged<br><i>Remarks: Recommend new wing</i>                                                                                                                                                                       | \$0.00 | \$0.00   | \$0.00    |
| 17.                  | Aircraft Reassembly and return to service                                                                                                                                                                                                                                                               | \$0.00 | \$0.00   | \$0.00    |
| <b>Miscellaneous</b> |                                                                                                                                                                                                                                                                                                         |        |          |           |
|                      | Shop Consumables Charge                                                                                                                                                                                                                                                                                 |        |          | \$21.75 T |

|                     |                |
|---------------------|----------------|
| LABOR               | \$217.50       |
| PARTS               | \$0.00         |
| MISC                | \$21.75        |
| SALES TAX @ 10.200% | \$24.40        |
| TOTAL               | \$263.65       |
| Payment Received    | \$239.69       |
| <b>Amount Due</b>   | <b>\$23.96</b> |