

WPR24LA092

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to main rotor blade (Courtesy of operator)