



Photo 1 – View of substantial damage to vertical stabilizer and rudder (Courtesy of Pilot)