

YEAR
20
DATE

RECORDING
TACH
TIME

TODAY'S
FLIGHT

TOTAL
TIME IN
SERVICE

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Model PA46-500TP
S/N 4697358
Reg # N26DR
WO# 28410

Interstate Turbine Management
6070 Perimeter Rd.
North Charleston, SC 29406

Date 6/17/2021
Hobbs 1586.4
TTAF 1586.4

Airframe: C/W annual inspection IAW Piper M/M. C/W FAR 91.207(d) ELT inspection. Installed new ELT battery P/N 455-0012, expiration date 06/2026. Serviced tires IAW Piper SL 1285A. C/W Piper SL 1286C NLG steering inspection and adjustment. C/W Piper SL 1202 and found MLG hoses serviceable. C/W Piper SL 1280A fire extinguisher inspection/replacement. New style fire extinguisher installed, no further action required. C/W Piper SL 1135 control cable pulley inspection. C/W Piper SL 1131A aileron sector bearing lubrication. C/W Piper SL 1338 MLG actuator attach fitting inspection and found helicoils properly installed. No further action required. C/W Piper SL 1233 wing/flap protective tape improvement. C/W Piper SL 1272 elevator spar inspection, no cracks noted. C/W Airborne SL 39A. C/W 24 month/400 hour fuel purge inspection. Replaced nose tire P/N 505C01-2. Replaced right main tire P/N 021-317-1. Replaced left and right brake linings P/N 066-06200. Removed EX5000 MFD compact flash card P/N 530-00201-000 rev 01 and installed new P/N 530-00201-000 rev 03 IAW Doc 601-00004-087. Tightened loose pitot line on standby indicator, leak checks good.

I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

CRS#