



Photo 1 – N601CF. Photo courtesy of the owner.



Photo 2 – Damaged engine mount. Photo courtesy of the owner.